



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

HSBC LIFE (SINGAPORE) PTE LTD

INV No. AC2304916

10 MARINA BOULEVARD #48-01 MARINA BAY
FINANCIAL CENTRE TOWER 2
SINGAPORE 018983
ATTN: HO WINNIE

INV Date 02/08/2023
Reference CS3/HSB23007390/Uqp3m4
Code HSB

PROFESSIONAL SERVICE FEE

Vehicle No. GBL 4477U
Insured Veh. SHC 1158L
Claim No. S3M04O8V
Policy No. VFX/P2419138
Accident Date 17/07/2023
Inspection Date 26/07/2023

| Description | Total |
|--|---------------|
| Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport) | 100.00 |
| Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 27.07.2023) | |
| Repaired vehicle before return to claimant as per NIMA Protocol (Photo taking + Transport on 31.07.2023) | |
| Subtotal | 100.00 |
| GST (8%) | 8.00 |
| Grand Total | 108.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

SML