

ASS. REC. BY:

REF:

Smoj

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

: Prell. Report

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

: Site Insp (\$

: Interview (\$

Tech Invs (\$

Weekend (\$

S - RS - SI

), Fines

), Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SMZ1843L
TP/Sompo

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623

TEL: 64616555

FAX: 62213302

ATTN: Motor Claim Department

WS Ref: TP/SOMPO

Claim Type: Third Party

Accident Date: 20/07/2023

TP Veh Reg No: SMH958R

Claim No: ES2300743

Estimate No: ES2300743/YISHUN

Date: 21 Jul 2023

Policy No: 5127247497-01

Veh Reg No: SMZ1843L

Make/Model: MITSUBISHI ATTRAGE
1.2 CVT

Chassis No: MMBSTA13AKH002658

Engine No: 3A92UHX8710

Reg. Date: 06/11/2019

Not with claim
Permy B4 pain
12 days

Estimate Repair Cost to Vehicle No : SMZ1843L

Description	U/Price	Quantity	Cost S\$	Amount S\$
Cost Plus				
1 REAR BUMPER	250.00	1 PC	250.00	1
2 REAR BUMPER SIDE RETAINER	14.00	2 PC	28.00	1
3 REAR BUMPER CLIP	2.50	6 PC	15.00	1
4 REAR BUMPER INNER GARNISH	25.00	2 PC	50.00	1
5 TAILLAMP	135.00	2 PC	270.00	1
6 REAR BOOT	320.00	1 PC	320.00	1
7 REAR BOOT LOGO	28.00	1 PC	28.00	1
8 REAR BOOT EMBLEM 'ATTRAGE'	22.00	1 PC	22.00	1
9 REAR BOOT EMBLEM 'MIVEC'	48.00	1 PC	48.00	1
10 REAR BOOT OUTER MOULDING	180.00	1 PC	180.00	1
11 REAR BOOT INNER LOCK	110.00	1 PC	110.00	1
12 REAR BOOT INNER RUBBER	55.00	1 PC	55.00	1
13 REAR BOOT HINGE	70.00	2 PC	140.00	1
14 REAR PANEL	240.00	1 PC	240.00	1
15 REAR PANEL TOP INNER GARNISH	45.00	1 PC	45.00	1
16 TAILLAMP PANEL	78.00	2 PC	156.00	1
17 REAR FENDER	440.00	2 PC	880.00	1
18 REAR COMPARTMENT PANEL TOP BOARD	100.00	1 PC	100.00	1
19 REAR COMPARTMENT PANEL TOP CUSHION	120.00	1 PC	120.00	1
20 REAR KEYLESS SENSOR	85.00	1 PC	85.00	1
21 REAR BUMPER LOWER SKIRT	500.00	1 PC	500.00	1
22 REAR WINDSCREEN GLASS MOULDING	200.00	1 PC	200.00	1
			3,842.00	
	Add 25%		960.50	4,802.50

Special Net

23 REVERSE CAMERA	350.00	1 SET	350.00	1
24 REVERSE SENSOR	200.00	1 SET	200.00	1
25 REAR NUMBER PLATE	35.00	1 PC	35.00	1
26 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	1
27 REAR BOOT SPOILER	380.00	1 PC	380.00	1
				1,005.00

Labour

28 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
---	--------	------	--------	---

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623

TEL: 64616555 FAX: 62213302
ATTN: Motor Claim Department

WS Ref: TP/SOMPO
Claim Type: Third Party
Accident Date: 20/07/2023
TP Veh Reg No: SMH958R

Claim No: ES2300743
Estimate No: ES2300743/YISHUN
Date: 21 Jul 2023
Policy No: 5127247497-01
Veh Reg No: SMZ1843L
Make/Model: MITSUBISHI ATTRAGE
1.2 CVT
Chassis No: MMBSTA13AKH002658
Engine No: 3A92UHX8710
Reg. Date: 06/11/2019

Estimate Repair Cost to Vehicle No : SMZ1843L

Description	U/Price	Quantity	Cost S\$	Amount S\$
29 REMOVE & REFIX REAR SEAT,CARPET,GARNISH, TOP ROOF LINING ETC	100.00	1 LA	100.00	✓
30 REMOVE & REFIX REAR BUMPER ASSY,BOOT,TAILLAMPS;TO STRAIGHTEN REAR BOTH CHASSIS,TO RENEW REAR BOTH FENDERS;KNOCKING & REPAIR REAR COMPARTMENT & REALIGN THE SAME	1,600.00	1 LA	1,600.00	1500
31 PUTTY & RESPRAY ON REAR SPOILER,REAR BUMPER,LOWER SKIRT,BOOT,HINGES,REAR COMPARTMENTS,REAR END PANEL,TAILLAMP PANELS,REAR BOTH FENDERS	1,400.00	1 LA	1,400.00	1200
32 REMOVE & REFIX REVERSE CAMERA,BLIND SENSOR & RESET SYSTEM	200.00	1 PC	200.00	120
33 RUSTPROOFING	90.00	1 LA	90.00	✓
				3,490.00

Total S\$ 9,297.50

Add GST @ 8% 743.80

Total Amount payable S\$ 10,041.30

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	20/07/2023 16:28 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	20/07/2023 08:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	SEMBAWANG AVE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMZ1843L

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	SIM ZHIXIANG JOEL
NRIC No	SXXXX143B
Email Address	joelsim@hotmail.com
Mobile Phone No	(Phone) +65-96806361
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Attrage
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	0

INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5127247497-01

DRIVER

Name of Driver	SIM ZHIXIANG JOEL
NRIC No	SXXXX143B
Date Of Birth	11/08/1987
Occupation	Indoor


MT/123768

Describe Circumstance of the Accident

NOTE: PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14 DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.

- () Claim Own Policy (✓) Claim Third party () Reporting Only
() Claim OD/ TP at other workshop ()

Sketch Plan



Sembawang Ave

On 20th July 2023, at around 8am, I was approaching a traffic junction along Sembawang Ave when I came to a stop when the traffic light turned Amber. A couple of seconds later I felt a car crash into the rear of mine. When I got up to inspect the damage, I saw that the car had been badly damaged as Car B had hit into the back of my car. There were no injuries.

Declaration

I/We declare the foregoing particulars are true in every respect.

 20/7/2023
1252 hrs
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

 20/7/23
Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)
(45)