



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

HSBC LIFE (SINGAPORE) PTE LTD

INV No. AC2304983

10 MARINA BOULEVARD #48-01 MARINA BAY
FINANCIAL CENTRE TOWER 2
SINGAPORE 018983
ATTN: LOW GARNET

INV Date 04/08/2023
Reference CS3/HSB23007464/Tvp3m4
Code HSB

PROFESSIONAL SERVICE FEE

Vehicle No. SLD 8790L
Insured Veh. SHD 3080H
Claim No. S3M04OD1
Policy No. VFX/P2419138
Accident Date 22/07/2023
Inspection Date 25/07/2023

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 26.07.2023)	
Repaired vehicle before return to claimant as per NIMA Protocol (Photo taking + Transport on 31.07.2023)	
Subtotal	100.00
GST (8%)	8.00
Grand Total	108.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

SML