

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SMR23007479/4943

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMX44756

at Workshop m/s Lee brook

of

Insured: SMB234C

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$100k.

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

3496

Vehicle: IN / OUT

Date: Person Contacted: LTA 836329

Veh No: SMX44756 Yr Regn: 13/01/21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Honda Shuttle C.C 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 144050 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GK 82101116

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195/55-R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Lessa

Front 6 Rear 6

R/Bal. mm R/Bal. mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 17/07/23 D.O.I. 25/7/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rec

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Dep 13k.

3-17/23 inbound AH ha: 2/5 86400 (Red \$ 3588.52, 367.7)

Date/Time, File Pass to?

1) 01/8 train

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 6400

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

Email: Sales@Leebrothers.com.sg

not full
all

25/7/23

2/5 # 6400
6 days

Vehicle Number: SMX4475G

Vehicle Model: HONDA SHUTTLE

PARTICULAR

AMOUNT

QTY

S\$

LIST PRICE

1	1	REAR WINDSCREEN MOULDING	all		\$	121.60 ✓
2	1	REAR TAILGATE	body	1193.40	\$	1,455.90 ✓
3	2	REAR TAILGATE HINGE -RH/LH @\$48.80	all		\$	97.60 X
4	2	REAR TAILGATE DAMPER -RH/LH @\$146.30	all		\$	292.60 X
5	1	REAR TAILGATE RUBBER	all		\$	226.90 ✓
6	1	REAR TAILGATE LOCK	all		\$	310.70 ✓
7	1	REAR TAILGATE LOCK CATCH	all		\$	29.30 X
8	1	REAR TAILGATE INNER TRIM	del trim		\$	481.90 ✓
9	1	REAR TAILGATE NUMBER PLATE GARNISH	one	366.50	\$	412.60 ✓
10	1	REAR TAILGATE EMBLEM 'H'	all		\$	48.80 ✓
11	1	REAR TAILGATE EMBLEM 'SHUTTLE'	all		\$	86.50 ✓
12	1	REAR TAILGATE REFLECTOR -RH	one		\$	409.50 ✓
13	1	REAR TAILLAMP -RH	one		\$	546.10 ✓
14	1	REAR TAILLAMP PANEL HOUSING -RH	R		\$	237.30 X
15	1	REAR BUMPER	D D	936.00	\$	1,210.60 ✓
16	1	REAR BUMPER TOW COVER	all		\$	28.20 X
17	1	REAR BUMPER REFLECTOR -RH	one		\$	74.10 ✓
18	1	REAR BUMPER MOULDING	scr		\$	216.20 ✓
19	2	REAR BUMPER SIDE RETAINER -RH/LH @\$65.90	all		\$	131.80 ✓
20	1	REAR END PANEL	body		\$	680.90 ✓
21	1	REAR END PANEL GARNISH	all		\$	261.20 ✓
22	1	REAR SPARE TYRE PANEL TRAY	all		\$	263.30 X
23	1	REAR FENDER INNER TRIM -RH	del trim		\$	555.80 ✓
					\$	8,179.40
					LESS 20%	\$ 1,635.88
						\$ 6,543.52

LEE BROTHERS AUTOMOTIVE PTE. LTD.

Vehicle Number: SMX4475G

Vehicle Model: HONDA SHUTTLE

PARTICULAR

AMOUNT

QTY

S\$

SPECIAL NETT ITEMS

1	REAR WINDSCREEN SPONGE TAPE	all	\$	20.00	✓
1	(SET) REAR WINDSCREEN SEALANT	rel	\$	80.00	40
1	REAR TAILGATE RUBBER SEAL	1-1	\$	180.00	80
1	REAR BUMPER TOP STEP STICKER	groab	\$	380.00	250
1	(SET) REAR BUMPER CLIP	rel	\$	45.00	40
			\$	705.00	

LABOUR CHARGES

TO KNOCK OUT DENT,CUT/WELD REAR PANEL, REAR TAILLAMP	\$	1,000.00	850
PANEL HOUSING AND REPLACE ACCIDENT PARTS	\$	1,200.00	1080
TO SPRAY PAINTING ON ACCIDENT PARTS	\$	30.00	20
TO CHECK WIRING	\$	120.00	✓
TO REMOVE & REFIX REAR WINDSCREEN	\$	100.00	60
TO TRANSFER REAR TAILGATE PARTS	\$	80.00	X
TO REMOVE & REFIX REVERSE CAMERA	\$	150.00	80
TO REMOVE & REFIX CUSHION AND INNER TRIM	\$	60.00	✓
TO TUFF KOTE	\$	2,740.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL :

\$ 9,988.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-6647-9
202
531832
430
2270
531832
202
6114