

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	STRIDES AUTOM	OTIVE SERVICES PTE LTD		Ref:	CS3/SMR23000142/Kny3m4-	
		INDUCTORAL DADIC			1	
	E4SINGAPORE 75	INDUSTRIAL PARK 57705		Date:	02/08/2023	
			(Code:	SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHB 5123R	Veh. Inspected		SJQ 7067D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/12/22/2082	Excess (\$)		0.00	
	Assign From	ASHLENE LEE	Assign Date		25/07/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA AIRWAVE (A)	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	GJ11304060	Colour		METALLIC GREY	
	Odometer	243783 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	175/65 R15	DUNLOP		8 mm	
	L/H Front Tyre	175/65 R15	DUNLOP		8 mm	
	R/H Rear Tyre	175/65 R15	DUNLOP		8 mm	
	L/H Rear Tyre	175/65 R15	DUNLOP		8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.					
	DAMAGES SEE D	DAMAGES SEE DETAILS.				
5.	General Information					
	Accident Date	31/12/2022	Inspection Date)	09/01/2023	
	Survey held at	YAP MOTOR SERVICE PTE LTI	D			
		BLK 7 SIN MING IND EST SEC				
5a.		#01-80 & 82 SINGAPORE 575642 Remarks				
Ju.	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.					
	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				