



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. GBK8840H TOYOTA DYNA 150T

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Wiper top panel <i>bl</i> ✓		368.00	
1	Front panel <i>bl</i> ✓		1218.00	
1	Front panel emblem "Dyna" <i>ku</i> ✓		62.00	
1	Front corner panel LH <i>?</i>		371.00	
1	Side mirror rectangle LH <i>broend</i> ✓		381.00	
1	Side mirror rectangle cover LH <i>cu</i> ✓		62.00	
1	Side mirror circle LH <i>ms</i> ✓		279.00	
1	Side mirror arm LH <i>bro</i> ✓		790.00	
1	Center grille <i>su</i> ✓		969.00	
1	Center grille logo badge <i>re</i> ✓		132.00	
1	Headlamp LH <i>su</i> ✓		979.00	
1	Front bumper <i>de</i> ✓		479.00	
1	Front bumper bracket LH <i>X</i>		371.00	
1	Fog lamp cover LH <i>X</i>		261.00	
Part Items Total:			6722.00	
			-25% -1680.50	
			5041.50	
SPECIAL NETT ITEMS				
1	Wiper top panel sealant <i>ku</i> ✓		60.00 30	
1	Front panel sealant <i>re</i> ✓		60.00 30	
1	Center grille clips <i>re</i> ✓		30.00	
1	Front bumper clips <i>re</i> ✓		35.00	
SN Items Total:			185.00	
Total Parts			5226.50	



Wah Heng Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahheng.sg

(199806235M)

Vehicle No. GBK8840H TOYOTA DYNA 150T

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00 700	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00 600	
3	To remove & refix wiring system at accident damaged area and check for all electrical proper function	90.00 50	
4	To perform anti-rust treatment on affected areas	90.00 40	
5	To remove, replace and focus headlamp	60.00 30	
Labour Total :		2040.00	
TOTAL (PARTS & LABOUR):		7266.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P. Heng
Hp 90010068

5 days

4/5

02/07/23

Resurvey after repair

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	328W
Vehicle No.:	GBK8840H
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Aug 2023
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2020
Engine No.:	1KDB066454
Chassis No.:	JTFAT35Y30K216125
Maximum Power Output:	-
Open Market Value:	\$29,446.00
Original Registration Date:	07 Jan 2021
First Registration Date:	07 Jan 2021
Transfer Count:	0
Actual ARF Paid:	\$1,473.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	06 Jan 2031
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$35,201.00
COE Rebate Amount:	\$26,145.00
Total Rebate Amount:	\$26,145.00

The information contained herein is correct as at 02 Aug 2023

OK

Toyota Dyna 150 3.0M

\$98,800 Instalment \$1,311/mth

PREMIUM AD

Shortlist

Loan Calculator



**KONNICHIWA!
OSAKA AWAITS!**



One-way from
\$199*

Book now
*Taxes included. Terms apply.


JNTO

Overview Financial Photo Research

Depreciation	 \$13,220 / year
Reg. Date	21-Jan-2021 (7yrs 5mths 18days COE left)
Lifespan	 20-Jan-2041
Manufactured	 2020
Mileage	-
Transmission	Manual
Engine Cap	2,982 cc
Curb Weight	 1,780 kg
Fuel Type	Diesel
COE	 \$27,121
OMV	 \$29,446
ARF	 \$1,473
Dereg Value	 \$20,270 as of today
No. of Owners	 1
Type of Veh	<u>Truck</u>