

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance
Management)
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 27 Jul 2023

Preliminary Advice

Vehicle No	: SML1135X	Accident Date	: 22/07/2023
Make	: OPEL INSIGNIA GRANDSPORT B16DTH	Policy No.	: SP2002451400
Assignment Date	: 25/07/2023	Excess	: S\$600.00
Date of Inspection	: 26/07/2023	Est. Duration of Repair	: 0
Inspection At	: PREMIER AUTOMOTIVE SERVICES PTE LTD (HQ) 60 JALAN LAM HUAT CARROS CENTRE, #07-43 SINGAPORE 737869		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	80,000.00
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	
Total	:S\$	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	94,000.00
COE / PARF Rebate	:S\$	41,393.00
Salvage Value	:S\$	
Margin for Repair	:S\$	52,607.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :