

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLA 13487

at Workshop m/s Lelcon Air Tamer

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: ?

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: \$54k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: LTA 829754

Veh No: SLA 13487 Yr Regn: 22/02/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA / 2.5

Make: Toyota Camry c.c. 2494

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 67289 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR 053 AK 500 4010610

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 215/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 22/07/23 D.O.I. 26/7/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s & o/s Rear

The U/C Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Dep 1400

Noted 824246

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	124A
Vehicle Details	
Vehicle No.:	SLA1348T
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jul 2023
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.5 AUTO
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	2ARU299270
Chassis No.:	MR053AK5004010610
Maximum Power Output:	133.0 kW (178 bhp)
Open Market Value:	\$29,296.00
Original Registration Date:	22 Feb 2016
First Registration Date:	22 Feb 2016
Transfer Count:	1
Actual ARF Paid:	\$33,015.00 16507
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Feb 2026
PARF Rebate Amount:	\$19,809.00
Intended COE Rebate Details	
COE Expiry Date:	21 Feb 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,610.00
COE Rebate Amount:	\$9,945.00
Total Rebate Amount:	\$29,754.00

The information contained herein is correct as at 26 Jul 2023

OK

Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

Low Interest Rate In-House Loan by GV Cars Financing



Flexible In-House Loan by GV
Cars Financing at 3.28% p.a.
Low Interest Rate.
GV Automobile Centre [StarAd](#)

Sort by [Date Posted](#) 20 results/page

15 vehicles



Toyota Camry 2.5

Any Category

[Advanced Search](#)[Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Camry 2.5		Any	Any	2016	Any	Any	Any	Available
	Toyota Camry 2.5A		<u>\$55,800</u>	\$14,790 /yr	23-Mar-2016	2,494 cc	-	Luxury	Available
Well maintained Camry! White colour never go wrong! Popular luxury sedan with powerful performance yet fuel efficient! Attractive loan...									
Posted: 26-Jul-2023									
	Toyota Camry 2.5A		<u>\$64,800</u>	\$16,630 /yr	21-Jun-2016	2,494 cc	120,120 km	Luxury	Available
Posted: 22-Jul-2023									
	Toyota Camry 2.5A		<u>\$59,800</u>	\$15,540 /yr	09-May-2016	2,494 cc	99,000 km	Luxury	Available
Rare One Owner unit. Valid road tax till Nov 2023. genuine mileage with servicing records to prove. Comfort & Power All In 1 Car. Perfec...									
WM Car Pte Ltd									
Posted: 21-Jul-2023									
	Toyota Camry 2.5A		<u>\$62,500</u>	\$15,840 /yr	21-Jun-2016	2,494 cc	61,000 km	Luxury	Available
1 owner only, low mileage unit. Pristine condition.									
Posted: 20-Jul-2023									
	Hanip Automobiles Pte Ltd - Specialist for Toyota Car repair, servicing & maintenance								
Hanip Automobiles is one of the few workshops in Singapore which is owned, run and operated by a former diagnostic specialist and master technician.									
More info about this shop									
	Toyota Camry 2.5A		<u>\$58,800</u>	\$16,490 /yr	17-Feb-2016	2,494 cc	65,000 km	Luxury	Available
One owner only, very well maintained & hardly drive with low mileage clock in. Experience timeless reliability and comfort with the Toyota...									
Posted: 18-Jul-2023									
	Toyota Camry 2.5A		<u>\$67,800</u>	\$15,680 /yr	02-Nov-2016	2,494 cc	85,000 km	Luxury	Available
Reliable & luxury white colour Toyota Camry 2.5A, buy with confidence 3 YEARS engine & gear box warranty provided, 3 free engine servi...									
Posted: 17-Jul-2023									
	Toyota Camry 2.5A		<u>\$65,800</u>	\$15,640 /yr	19-Sep-2016	2,494 cc	160,000 km	Luxury	Available
1 owner, Borneo Motors serviced since day 1! Regularly serviced! 100% accident free unit! Very well maintained! In house financing and...									
Hui Hua Credit Pte Ltd									
Posted: 17-Jul-2023									

[Compare](#)

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Jul 2023)
Parts: 143 TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Falcon-Air Auto Services Pte Ltd/SLA1348T/26/07/2023 10:52
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOT COVER R	0.00	0.00	*410.00 F X
2	1		*BOOT LOGO 11	0.00	0.00	*32.00 F X
3	1		*BOOT EMBLEM (CAMRY) der	0.00	0.00	*32.00 F ✓
4	1		*BOOT EMBLEM (2.5) der	0.00	0.00	*30.00 F ✓
5	1		*O/S BOOT REFLECTOR one	0.00	0.00	*195.00 F ✓
6	1		*BOOT INNER TRIM CLIPS 11	0	0.00	*40.00 FS X
7	1		*O/S TAILLAMP one	0.00	0.00	*205.00 F ✓
8	1		*O/S TAILLAMP CLIPS 11	0	0.00	*20.00 FS X
9	1		*REAR BUMPER Dis	0.00	0.00	*320.00 F ✓
10	1		*O/S REAR BUMPER SIDE RETAINER der	0.00	0.00	*65.00 F ✓
11	1		*REAR BUMPER CLIPS der	0	0.00	*40.00 FS ✓
12	1		*REAR BUMPER RIVETS 11	0	0.00	*60.00 FS X
13	1		*O/S REAR BUMPER REFLECTOR 1/20	0.00	0.00	*50.00 F ✓
14	1		*REVERSE SENSOR	0.00	0.00	*320.00 F ?
15	1		*REAR BUMPER UNDERCOVER	0.00	0.00	*220.00 F ?
16	1		*REAR BUMPER UNDERCOVER CLIPS	0	0.00	*40.00 FS ?
17	1		*EXHAUST SILENCER 20 1/2 der	0.00	0.00	*360.00 F ✓
18	1		*EXHAUST SILENCER CHROME COVER der	0.00	0.00	*105.00 F ✓
19	2		*EXHAUST SILENCER MOUNTING 20 1/2	0.00	0.00	*60.00 F ✓
20	1		*EXHAUST SILENCER HEAT SHIELD der	0.00	0.00	*125.00 F ✓
21	2		*EXHAUST SILENCER GASKET der	0.00	0.00	*76.00 F ✓
22	1		*EXHAUST CENTER PIPE der/1/20 p/b	0.00	0.00	*340.00 F ✓
23	2		*EXHAUST CENTER PIPE MOUNTING	0.00	0.00	*60.00 F ?
24	2		*EXHAUST CENTER PIPE GASKET 11	0.00	0.00	*76.00 F X
25	1		*EXHAUST CENTER PIPE HEAT SHIELD	0.00	0.00	*170.00 F ?
26	1		*EXHAUST CENTER PIPE HEAT SHIELD CLIPS 11	0	0.00	*40.00 FS X
27	1		*O/S REAR DOOR 20	0.00	0.00	*550.00 F ✓
28	1		*O/S REAR DOOR TAPE der	0.00	0.00	*60.00 F ✓
29	1		*O/S REAR DOOR INNER TRIM CLIPS 11	0	0.00	*40.00 FS X
30	1		*REAR BUMPER REINFORCEMENT	0.00	0.00	*190.00 F ?
31	1		*O/S ROCKER PANEL GARNISH	0.00	0.00	*320.00 F ?
32	1		*O/S ROCKER PANEL GARNISH CLIPS 11	0	0.00	*40.00 FS X
33	1		*O/S REAR FENDER INNER SHIELD 20 1/2	0.00	0.00	*180.00 F ✓
34	1		*O/S REAR FENDER INNER SHIELD CLIPS	0	0.00	*40.00 FS ?
35	1		*O/S REAR FENDER INNER SHIELD BRACKET	0.00	0.00	*80.00 F ?
36	1		*O/S REAR RIM 20 1/2 50 5/2	0.00	0.00	*1,650.00 F ✓
37	1		*O/S REAR TYRE 11	0	0.00	*380.00 FS X
38	1		*O/S REAR SHOCK ABSORBER	0.00	0.00	*195.00 F ?
39	1		*O/S REAR SHOCK ABSORBER	0.00	0.00	*295.00 F ?
39	1		*O/S REAR KNUCKLE ARM	0.00	0.00	*320.00 F ?
40	1		*O/S REAR WHEEL HUB	0.00	0.00	*190.00 F ?
41	1		*O/S REAR CONTROL ARM (BOTTOM)	0.00	0.00	*210.00 F ?
42	1		*O/S REAR CONTROL ARM TOP (BIG)	0.00	0.00	*195.00 F ?
43	1		*O/S REAR CONTROL ARM TOP (SMALL)	0.00	0.00	*75.00 F ?
44	1		*O/S REAR LINKAGE	0.00	0.00	*240.00 F ?
45	1		*REAR ANTI ROLL BAR			

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*REAR CROSSMEMBER	0.00	0.00	*780.00 F 7
47	2		*REAR CROSSMEMBER BRACKET	0.00	0.00	*190.00 F 7
48	1		*O/S REAR LEVEL SENSOR LINKAGE	0.00	0.00	*350.00 F 7

F=Franchise part. S=SpcNett.

Sub Total (S\$)	10,061.00
+ Margin on L,N Items 15.00% (S\$)	1,398.15
Total Parts (S\$)	11,459.15

Falcon-Air Auto Services Pte Ltd/SLA1348T/26/07/2023 10:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CHECK REAR WIRING	New 20	50.00
2	TO TRANSFER BOOT COVER MECHANISM	New 12 X	120.00
3	TO FIT REVERSE SENSOR ON NEW BUMPER	New 40	50.00
4	TO TRANSFER O/S REAR DOOR GLASS TO NEW DOOR	New 50 L	120.00
5	TO TRANSFER O/S REAR DOOR MECHANISM TO NEW DOOR	New	120.00
6	TO REPLACE AND RE-ALIGN EXHAUST SYSTEM	New 80	350.00
7	TO REPLACE NEW TYRE TO NEW RIM INCLUDE BALANCING	New 12 X	50.00
8	TO REPLACE O/S REAR UNDERCARRIAGE AND REAR CROSSMEMBER	New 300 ?	500.00
9	TO CONDUCT 4 WHEEL ALIGNMENT	New 80	120.00
10	TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, REPLACEMENT OF PARTS AND ALIGN THE SAME	New 600	1,200.00
11	TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA	New 1000	1,800.00
Gross Labour Cost (S\$)			4,480.00

Falcon-Air Auto Services Pte Ltd/SLA1348T/26/07/2023 10:52. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg