

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Jul 2023)

Parts: 144 TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SH6470U/26/07/2023 10:20

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER			
2	1		*REAR BUMPER LOWER COVER	25.00	0.00	de *503.04 FL
3	1		*REAR BUMPER REINFORCEMENT	25.00	0.00	de *654.96 FL
4	2		*REAR BUMPER RETAINER LH/RH	25.00	0.00	nn *378.32 FL
5	10		*REAR BUMPER CLIPS	25.00	0.00	nn *225.40 FL
6	1		*REAR BUMPER TOW HOOK COVER	25.00	0.00	nn *22.00 FL
7	1		*TAIL GATE TOYOTA EMBLEM	25.00	0.00	de *82.70 FL
8	1		*TAIL GATE HYBRID EMBLEM	25.00	0.00	nn *81.43 FL
9	1		*TAIL GATE PRIUS EMBLEM	25.00	0.00	nn *62.14 FL
10	1		*REAR BUMPER ADVERTISEMENT	25.00	0.00	nn *62.14 FL
11	1		*REAR BUMPER MAT	0	0.00	nn *50.00 FS
12	1		*REAR REVERSE SENSOR	0	0.00	nn *50.00 FS
13	1		*REAR COMFORT APP STICKER	0	0.00	nn *135.70 FS
14	1		*REAR COMFORT LOGO/ TEL NO. STICKER	0	0.00	nn *40.00 FS
				0	0.00	nn *80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 1386.98

- List Item Discount on L Items (\$\$) 1086.84

2,427.83

518.03

Total Parts (\$\$) SN 276.50

1,909.80

ComfortDelGro Engineering Pte Ltd/SH6470U/26/07/2023 10:20. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

1363.34

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	350 700.00
2	SPRAY PAINTING	New	500 600.00
3	REMOVE/REFIX REVERSE SENSOR	New	30 60.00
4	TUFF COATING	New NN X	60.00
Gross Labour Cost (S\$)			880 1,420.00

ComfortDelGro Engineering Pte Ltd/SH6470U/26/07/2023 10:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

2243.34
l/s1800
2 days #

Tanpin 97495749
'wp' 27/7/23 2pm
l/s Resurvey after repair
Tanpin C / Markson
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature
Date