

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Estimate No: EST2300278
Date: 25 Jul 2023
Veh Reg No: SMR2879U
Make/Model: HONDA VEZEL 1.5X
CVT
Chasis No: RU11325034
Reg. Date: 27/12/2019
Your Ref No: GBL8292J

Claim Type: Third Party
Accident Date: 12/07/2023
TP Veh Reg No: GBL8292J

Estimate Repair Cost to Vehicle No :SMR2879U

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC REAR BUMPER	863.70	
2	1 PC REAR BUMPER RETAINER - LH	41.40	
3	1 PC REAR BUMPER REFLECTOR - LH	161.40	
4	1 PC REAR BUMPER SIDE LH	201.70	
5	1 PC TAIL LAMP LH	564.90	
6	1 PC REAR LH FENDER ARC GARNISH	187.60	
7	1 PC REAR PANEL	493.60	
		2,514.30	
	Less 20%	502.86	2,011.44
	Special Net		
8	1 SET REAR BUMPER CLIPS	60.00	
9	1 SET REVERSE SENSORS	250.00	
10	1 SET REAR LH ARC GARNISH CLIPS	40.00	
		350.00	350.00
	Labour		
11	1 TO CHECK WIRING	50.00	
12	1 (REAR) TO SPRAY PAINTING	800.00	
13	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	750.00	
		1,600.00	1,600.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 12/07/2023
TP Veh Reg No: GBL8292J

Estimate No: EST2300278
Date: 25 Jul 2023
Veh Reg No: SMR2879U
Make/Model: HONDA VEZEL 1.5X
CVT
Chasis No: RU11325034
Reg. Date: 27/12/2019
Your Ref No: GBL8292J

Estimate Repair Cost to Vehicle No :SMR2879U

Quantity	Description	List Price	Amount
		S\$	S\$
	Total		S\$ 3,961.44
	Add GST @ 8%		316.92
	Total Amount Payable		<u>S\$ 4,278.36</u>

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND TWO HUNDRED SEVENTY EIGHT AND CENTS THIRTY SIX ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE