COTAL

# **BIFROST AUTO PTE LTD**

Not Notherson 1/Ray 8 Resury Afar Paint 12-16day

# REPAIR ESTIMATE

DATE:

27-Jul-23

INSURANCE:

MODEL:

TOYOTA PRIUS

VEHICLE NO .:

SHC 3879 B

DESCRIPTION	150	QTY	LIST PRICE	AMOUNT
REAR TRUNK LID COVER	B	1	\$1,303.29	\$1,303.29
EAR TRUNK LID LOCK	p	11	\$530.79	\$530.79
EAR TRUNK LID LOCK COVER	a	71	\$ 129.80	\$ 129.80
REAR TRUNK LID LOCK SWITCH	P-	1	\$ 468.90	\$ 468.90
EAR TRUNK LID COVER TRIM BOARD	mg 1	111	\$254.40	\$254.40
Soot Lid Trimboard,Centre		_1	يم \$159.60	\$ 159.60
Boot Lid Trimboard SIDE (LH/RH)	h	2	\$92.50	\$ 185.00
Boot Lid Trimboard REAR		1	\$124.80	\$ 124.80
BOOT HANDLE	h	1	\$31.80	\$31.80
REAR TRUNK LID RUBBER	1ij	121	\$365.20	\$365.20
REAR TRUNK LID GLASS (BLACK COLOR)	Shothere	1 1	\$969.70	\$969.70
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	cn	1 1	\$1,054.71	\$1,054.71
REAR TRUNK LID LOGO (PRIUS)	M	1	\$62.14	\$62.14
REAR TRUNK LID LOGO (HYBRID)	Ne	1	\$62.14	\$62.14
REAR TRUNK LID LOGO (TOYOTA STAR)	Ne	1	\$81.43	\$81.43
THIRD BRAKE LIGHT	s	1	\$394.70	\$394.70
REAR TRUNK LID STRIKER	1	<b>K</b> 1	\$98.70	\$98.70
REAR TRUNK LID HINGE (LH/RH)	4	K 2	\$189.50	\$379.00
REAR TRUNK LID ABSORBER (LH/RH)		2	\$287.50	\$575.00
REAR TRUNK LID ABSORBER BRACKET (LH/RH)	J	2	\$127.90	\$255.80
REAR TRUNK LID STOPPER (LH/RH)	M	_	\$84.80	\$169.60
SPOILERSUB-ASSY , REAR	S	1	\$1,787.79	\$1,787.79
REAR WINDSCREEN GLASS W/ MOULDING		1	\$1,884.32	\$1,884.32
REAR NO. PLATE LAMP LH/RH	Su	_	\$163.50	\$327.00
REAR BUMPER	R		\$503.04	\$503.04
REAR BUMPER RE-INFORCEMENT	n	1 1	\$378.32	\$378.32

		•		1
REAR BUMPER LOWER COVER 197	1	\$654.96	\$654.96	<u>ー</u>
REAR BUMPER SIDE RETAINER CON	2	\$112.70	\$225.40	_
REAR BUMPER TOWING COVER	<b>-</b> 1	\$82.70	\$82.70	X
REAR BUMPER CLIPS	<b>ኒ</b> 1	\$22.00	\$22.00	
REAR BUMPER SIDE CLIP	2	\$25.00	\$50.00	~
REAR BUMPER UPPER STOPPER (LH/RH)	2	\$76.40	\$152.80	7
SEAL, REAR BUMPER SIDE, LH/RH ALAIT	2	\$148.40	\$296.80	4
REAR BUMPER UNDER SIDE COVER (LH/RH)	2	\$232.00	\$464.00	0117
ARM SUB-ASSY, REAR BUMPER, (LH/RH)	2	\$139.60	\$279.20	4
REAR BUMPER REVERSE SENSOR Short	1	\$235.70	\$235.70	<u> </u>
REAR BUMPER UNDER COVER (CENTER) 1.7	12	\$773.64	\$1,547.28	4
TO BE THE STATE OF	2	\$557.90	\$1,115.80	_
in a all and	2		\$1,140.00	
	2000	\$570.00	\$1,140.00	_
TAIL LAMP QUARTER PANEL  TAIL LAMP SIDE COVER PM  Mill and Mill an	1	\$216.00		~
A A	2000	\$256.00	\$256.00	
A		\$95.30	\$95.30	
nert Etter / title	1	\$738.96	\$738.96	_
REAL END PAREE ON CHOICE	1	\$294.80	\$294.80	?
REAR SPARE TYRE PANEL  DEAD END DANEL GARNISH COVER  70	1	\$960.80	\$960.80	
REAR END PANCE CARMION GOVER		\$ 138.90	\$138.90	7
REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)	2	\$668.90	\$668.90	<u>.</u>
REAR FIBER TOOL BOX TRIM (CITITAT)		\$598.00	\$1,196.00	
NEW TOOL BOX OF WELL	1 1	\$186.20	\$186.20	7
SPARE TYRE LOCK NUT	1	\$88.40	\$88.40	7
SPARE TYRE LOCK NUT BRACKET	1	\$113.50	\$113.50	7
SPARE TYRE SIDE PANEL (LH)	1	\$287.30	\$287.30	
REAR FENDER, LH	6.26	\$992.04	\$992.04	
REAR FENDER SHIELD (LH)	1	\$174.20	\$174.20	_/
REAR FENDER TRIMBOARD (LH)		\$725.00	\$725.00 \$165.10	_
REAR FENDER AIR DUCT	_	\$165.10	\$1,117.93	
	21	\$1,117.93 \$398.10		(
	<u>1</u>	\$396.10		<del>`</del>
INSULATOR CLIPS 10 PCS	n1	\$35.50	\$35.50 ×	e 3
BONNET RUBBER	1 2	\$87.70	\$175.40 X	
BONNET HINGE (LH/RH)	1 1	\$132.60	\$132.60	
BONNET LOCK  PLANTING AND ANY HOOK		\$8.60	\$8.60 X	

RADIATOR GRILLE C	M	1	8	\$438.00	\$438.00	] —
RADIATOR GRILLE EMBLEM	2	1		\$88.00	\$88.00	1
FRONT BUMPER COVER	3,	1	f).	\$591.75	\$591.75	] _
FRONT BUMPER REINFORCEMENT	3	1		\$812.89	\$812.89	] -
FRONT BUMPER REINFORCEMENT ABSORBER	-	. 1		\$115.70	\$115.70	س [
RONT BUMPER LOWER REINFORCEMENT	٦	1		\$364.20	\$364.20	17
T BUMPER LOWER REINFORCEMENT BRACKET LH/RH	ヿ	2		\$330.00	\$660.00	7
ABSORBER, FRONT BUMPER, LOWER	ヿ	1		\$127.70	\$127.70	1
FRONT SIDE MEMBER REINFORCEMENT PANEL (LH/RH)	1			\$ 320.70	\$641.40	×
	<u>_</u>	2		\$ 172.50	\$345.00	<b>X</b>
	m	11.55		\$78.80	\$78.80	ر.ا
	1000	n 1		\$193.18	\$193.18	_
LAMP ASSY, FOG, RH	P	1		\$920.00	\$920.00	X
The second secon	4	•	7	\$920.00	\$920.00	X
The second secon	M		7	\$99.00	\$99.00	_
The second of th	0/1	/ 2	$\exists$	\$77.00	\$154.00	レ
FRONT LOWER PANEL	Ť	1		\$320.65	\$320.65	7
The state of the s	4	2		\$230.80	\$461.60	X
FRONT LOWER CROSSMEMBER		1	$\neg$	\$357.70		7
	1.	1		\$180.80	\$180.80	X
FRONT BUMPER TOP GARNISH	1	- 1		\$225.40	\$225.40	X
UNIT ASSY, HEADLAMP, RH (LED)	7/1			\$3,455.00	\$3,455.00	_
UNIT ASSY, HEADLAMP, LH (LED)	21	1		\$3,455.00	\$3,455.00	_
HEAD LAMP PANEL (RH)	T	1		\$240.10	\$240.10	7
HEAD LAMP PANEL (LH)	T	1		\$240.10	\$240.10	7
TOP PANEL CENTRE	n	1		\$364.98	\$364.98	_
TOP PANEL SIDE		2		\$145.90	\$291.80	7
BRACE PANEL		1		\$75.20	\$75.20	?
RADIATOR ASSY		1		\$1,841.80	\$1,841.80	7
RADIATOR FAN MOTOR ASSY		1		\$1,093.90	\$1,093.90	7
DEFLECTOR, RADIATOR SIDE, RH	$\perp$	1		\$83.50	\$83.50	
DEFLECTOR, RADIATOR SIDE, LH	$\perp$	1		\$83.50	\$83.50	
HORN (1 PC)	$\perp$	2	4	\$112.71	\$225.42	1504
CONDENSER ASSY, W/RECEIVER	$\perp$	1		\$1,336.60	\$1,336.60	
	2	1	$\perp$	\$1,111.93	\$1,111.93 X	
FRONT FENDER SHIELD	$\neg$	1		\$255.00	\$255.00 X	
FRONT FENDER SHIELD CLIP	N	1		\$14.90	\$14.90	

RONT FENDER HYBRID EN	MBLEM, LH	N	~	1	\$86.5	50	\$86.50
RACKET, FRONT SIDE PAI	NEL, LH		n	1	\$86.3	30	\$86.30
XTENSION, FRONT FENDE	R, LH		K	1	\$47.2	20	\$47.20
ROTECTOR, FRONT FEND	ER UPPER, LH		52	1	\$46.1	0	\$46.10
USSET, FRONT FENDER	APRON, LOWER LH		15	1	\$34.9	90	\$34.90
RONT APRON TO COWL S	IDE, LOWER FRT LH		2	1	\$82.3	30	\$82.30
							,
JB TOTAL						2	50,653.7
ESS 20%		1					10,130.7
ISCOUNTED TOTAL							40,522.9
SOSSINIED TOTAL						<b>—</b>	10,022.0
EVERSE CAMERA ASSY			SN	1	\$380.	00	\$380.00
EAR TRUNK LOWER W/S	MOULDING	M	SN	1	\$180.	00	\$180.00
EAR LOWER W/S SEALAN	NT	Na		1	\$46.0	0.00	\$46.00
EAR WINDSCREEN SEAL	w///a/C2	Ma		1	\$46.0		\$46.00
EAR NO. PLATE WITH CO	OVER	B		1	\$100.0		\$100.00
EAR TRUNK LID APPS ST	to the afficiency of	nec		1	\$40.0		\$40.00
REAR TRUNK LID COMFORT & TEL NO. STICKER		M	SN	1	\$60.0		\$60.00
FRONT NO. PLATE		558	∕SN	1	\$25.0		\$25.00
RONT NO. PLATE TRIM C	OVER	cm	-	1	\$30.0	0	\$30.00
COOLANT	LKK Auto Consulta	nts benc	e3blify	1	\$45.0	0	\$45.00
	the Repairer of the  To resurvey before/aite						
SUB TOTAL	To display damaged pa     Parts prices are subject	art(s) durin	ng resurv	ву			\$952.00
JOB TOTAL	Third party survey is on a "Without Prejud     No illegal modification(s) is allowed			ice" basis			
Labour Charge	<ul> <li>Supplementary item(s)</li> </ul>	must be r	resurvey	d and			
Panel Beating	is subject to final appro		nourance	Company 1	\$2,600.0	00	\$2,600.00
Spray Painting Charge	Acknowledged by Repair Signature:	er		1	\$2,200.0	00 :	\$2,200.00
Wiring Charge	Date:			1	\$100.0	00	\$100.00
Tuff Kote				1	\$100.0	00	\$100.00
(Bill)			1	\$80.0	00	\$80.00	
Towing Charge  Remove/Refix Cushion & Upholstery Rear			1	\$150.0	00	\$150.00	
Remove/Refix Cushion & Ophoistery Real Remove/Refix Rear Windscreen Glass			2	\$120.0	00	\$240.00	
Remove/Refix Rear Windscreen Glass Remove/Refix Radiator			1	\$90.0	0	\$90.00	
Remove/Refix Aircon & Refill Gas			1	\$130.0	0	\$130.00	
Diagnostic & Resetting To Erase Fault Code			1	\$550.0	0	\$550.00	
Diagnosic & Resetting 10 E						+-	0.240.00
						\$	6,240.00

# > Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** 

Vehicle Owner Particulars				
Owner ID Type:	Company			
Owner ID: Vehicle Details	821R			
Vehicle No.:	SHC3879B			
Vehicle to be Exported:	No			
Intended Deregistration Date:	31 Jul 2023			
Vehicle Make:	TOYOTA			
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)			
Primary Colour:	Blue			
Manufacturing Year:	2018			
Engine No.:	2ZR2C27058			
Chassis No.:	JTDKB3FU303081248			
Maximum Power Output:	90.0 kW (120 bhp)			
Open Market Value:	\$26,605.00			
Original Registration Date:	31 May 2019			
First Registration Date:	31 May 2019			
Transfer Count:	0			
Actual ARF Paid: Intended PARF Rebate Details	\$14,247.00			
PARF Eligibility:	Yes			
PARF Eligibility Expiry Date:	30 May 2027			
PARF Rebate Amount: Intended COE Rebate Details	\$10,685.00			
COE Expiry Date:	30 May 2027			
COE Category:	A - Car up to 1600cc & 97kW (130bhp)			
COE Period(Years):	8			
PQP Paid:	\$22,309.00			
COE Rebate Amount:	\$10,682.00			
Total Rebate Amount: Message	\$21,367.00  further renewed. The vehicle must be de-registered upon COE expiry or when the			

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 Jul 2023

SJ0G237R000Q / JP Knights Pte Ltd ENTRY DATE & TIME: 27/07/2023 14:50 (SGT) SUBMITTED BY: Welne Chieng VERSION: 1 (27/07/2023 14:50 (SGT))

# **C** SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

Please report correctly the details of the accident to speed up the claims process
 This Form must be completed by the Policyholder and/or the Actual Driver

2. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any falsa reporting may be referred to the Police for investigation.
 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by Interested parties.
 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesald.

### ACCIDENT STATEMENT

Date of First Submission Reported by **Date of Accident Exact Location of Accident** Additional Location Information Country/State of Loss

27/07/2023 14:50 (SGT) **Actual Driver** 27/07/2023 00:35 (SGT) Kampong Java Tunnel, Singapore **TOWARDS SLE** Singapore

## **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

SHC3879B

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No **Email Address** Mobile Phone No. Alternative Phone No

Yes COMFORT TRANSPORTATION PTE LTD 1XXXXX821R fleetsafety@cdgtaxi.com.sg (Phone) +65-90991710 (Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer Model Variant

Exact purpose for which vehicle was being used at time of Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category Transmission

CC

Private hire

Toyota

Prius

No - Claiming third party

Taxi Auto 1798

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number HSBC Life (Singapore) Pte. Ltd VFX/P2419138

DRIVER

Name of Driver NRIC No Date Of Birth Occupation

TAN KOK BOON SXXXX090Z 19/04/1964 Outdoor

Accident report SJ0G237R000Q

SKETCH PLAN

## SKETCH PLAN

## IMPORTANT NOTICE

- 1. Please correctly report the details of the accident to speed up the cialms process.
- 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

lunderstand, acknowledge, agree and consent that:

(a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims

(i) investigating the accident and/or my claims.

(ii) carrying out ancior dealing with my instructions or responding to any enquiries by me

(including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (Collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect. use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third-party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Driver's Signature (If driver is not the policyholder) / Data & Time 27.07.2023. 1320HRS

FLASH ACCIDENT REPORTING OFFICE KYMI

Witnessed by Reporting Centre Personnel

Sketch Plan

Time

Policyholder's Signature i Date &

CTE / SLE KAMPONG JAVA TUNNEL A - SHC3879B B - SKX2496H C - 5JX9938R





Report N

Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

CONTINUATION OF REPORT

wake up the pain more worse so i consult doctor and was given 5 days MC.