



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

HSBC LIFE (SINGAPORE) PTE LTD

INV No. AC2304966

10 MARINA BOULEVARD

INV Date 03/08/2023

#48-01 MARINA BAY FINANCIAL CENTRE

Reference CS3/HSB23007687/Tnp3e2

TOWER 2

Code HSB

SINGAPORE 018983

ATTN: LOH CYNTHIA

PROFESSIONAL SERVICE FEE

Vehicle No. SJR 8493U

Insured Veh. SHA 4513K

Claim No. S3M04OB7

Policy No. VFX/P2419138

Accident Date 20/07/2023

Inspection Date 01/08/2023

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 01.08.2023)	
Subtotal	100.00
GST (8%)	8.00
Grand Total	108.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM