

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	HSBC LIFE (SING	APORE) PTE LTD		Ref:	CS3/HSB23007687/Tnp3e2
	10 MARINA BOULE #48-01 MARINA BA 2SINGAPORE 018		Date:	03/08/2023	
	ATTN: LOH CYNTH	HIA		Code:	HSB
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 4513K	Veh. Inspected		SJR 8493U
	Policy No.	VFX/P2419138	Coverage (\$)		0.00
	Claim No.	S3M04OB7	Excess (\$)		0.00
	Assign From	LOH CYNTHIA	Assign Date		31/07/2023
2. Vehicle Particulars & Condition					
	Make & Model	HONDA FREED	c.c		1496
	Engine No.	HIDDEN	Year of Reg.		2009
	Chassis No.	GB31034942	Colour		WHITE
	Odometer	130042 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	215/45 R17	MICHELIN		6 mm
	L/H Front Tyre	215/45 R17	MICHELIN		6 mm
	R/H Rear Tyre	215/45 R17	MICHELIN		6 mm
	L/H Rear Tyre	215/45 R17	MICHELIN		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
5.	General Information				
	Accident Date	20/07/2023	Inspect Date / 1	Time	01/08/2023 ( 11:00 AM )
	Survey held at	SUPER MODERN SERVICES			
	25 KAKI BUKIT ROAD 4 #01-26 SYNERGY @ KB SINGAPORE 417800				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/HSB23007687/Tnp3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.