



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0728/2023/EQ
DATE : 2-Aug-23
WIP : 31338

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 3/8/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR HO SHUI CHOY (HE SHUCAI)
ADDRESS : 90 PUNGGOL CENTRAL
#13-22
SINGAPORE 828722
TELEPHONE : HP +65 96336072
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220122576
VEHICLE NO : **SJP 7628 R**
MODEL CODE : AUDI E-TRON 50 QUATTRO
MODEL YEAR : 28/10/2022
ENGINE NO : EAS 174888
CHASSIS NO : WAUZZZGE2PB001990
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 31-Jul-23
PLACE OF ACCIDENT : MULTI-STOREY CARPARK AT NCS HUB

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJP 7628 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 450.00	
3	TO CARRY OUT DE-ENERGEISING HIGH VOLTAGE SYSTEM, DEACTIVATION AND ACTIVATION.	S/N \$ 480.00	
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,700.00	
5	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ 2,500.00	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ <u>6,802.00</u>	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJP 7628 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 3,066.00	
2	FRONT BUMPER TRIM - LH / RH	2	\$ 138.00	
3	FRONT BUMPER FIXING PARTS	1	\$ 689.00	
4	FRONT BUMPER FOAM PART - LH	1	\$ 36.00	
5	FRONT BUMPER SUPPORT COVER - LH	1	\$ 41.00	
6	FRONT BUMPER FOAM PART - LOWER	1	\$ 133.00	
7	FRONT BUMPER FOAM PART - UPPER	1	\$ 159.00	
8	FRINT BUMPER PLASTIC FOAM STRIP	1	\$ 143.00	
9	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 300.00	
10	FRONT BUMPER GRILLE - CENTER	1	\$ 181.00	
11	FRONT BUMPER CLOSING ELEMENT - LOWER	1	\$ 248.00	
12	FRONT BUMPER AIR GUIDE - LH	1	\$ 107.00	
13	FRONT BUMPER IMPACT PROTECTION	1	\$ 953.00	
14	FRONT BUMPER SPOILER - LH	1	\$ 117.00	
15	FRONT BUMPER AIR GUIDE - LH OUTER	1	\$ 64.00	
16	FRONT BUMPER AIR GUIDE - LH INNER	1	\$ 50.00	
17	FRONT BUMPER AIR GUIDE - LH	1	\$ 141.00	
18	FRONT BUMPER GUIDE SECTION - LH	1	\$ 53.00	
19	FRONT BUMPER TOP COVER - UPPER	1	\$ 126.00	
20	FRONT BUMPER TOP COVER - LOWER	1	\$ 125.00	
SUB TOTAL SPARE PARTS			\$ 6,870.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJP 7628 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	CAUTION NOTICE	1	\$ 24.00	
22	HEADLIGHT - LH	1	\$ 9,177.00	
23	LIFT CYLINDER - LH	1	\$ 274.00	
24	LIFT CYLINDER HOSE	1	\$ 115.00	
25	FRONT PARKING AID SENSOR - LH	1	\$ 299.00	
26	FRONT PARKING AID SEAL RING	4	\$ 11.00	
27	FRONT FENDER - LH	1	\$ 2,620.00	
28	FRONT FENDER BRACKET - LH	1	\$ 100.00	
29	HEADLIGHTS SEAL - LH	1	\$ 63.00	
30	FRONT FENDER BRACKET - LH FRONT	1	\$ 12.00	
31	FRONT FENDER BRACKET - LH CENTRE	1	\$ 16.00	
32	FRONT FENDER BRACKET - LH REAR	1	\$ 16.00	
33	FRONT WHEEL HOUSING LINER - LH	1	\$ 322.00	
34	RADIATOR AIR GUIDE BRAKE - LH	1	\$ 54.00	
35	FRONT SPOILER - LH	1	\$ 112.00	
36	FRONT WHEEL COVER - LH / RH	2	\$ 686.00	
37	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 21,171.00	
TOTAL LABOUR CHARGES		:	\$ 6,802.00	
GRAND TOTAL		:	\$ 27,973.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT