

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
 AIG Building
 78 Shenton Way #07-16
 Singapore 079120

From: LKK Auto Consultants Pte Ltd
 51 Ubi Ave 1 #01-25
 Paya Ubi Industrial Park
 Singapore 408933

Attn: Hiew, Chasin

Date: 04 Aug 2023

Preliminary Advice

Vehicle No	: SJP7628R	Accident Date	: 31/07/2023
Make	: AUDI E-TRON	Policy No.	: 7220122576
Assignment Date	: 01/08/2023	Excess	: S\$1,200.00
Date of Inspection	: 03/08/2023	Est. Duration of Repair	: 3
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,973.00
Revised Amount	:S\$	16,601.00
Check Items (Estimated)	:S\$	867.00
Total	:S\$	17,468.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	295,000.00
COE / PARF Rebate	:S\$	136,028.00
Salvage Value	:S\$	
Margin for Repair	:S\$	158,972.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.