

SNC3989X - Submitted by: LKK Auto Consultants Pte Ltd (HQ)

1/22: Odometer Reading



2/22: Chassis Number



3/22: General View

SNC3989X - Submitted by: LKK Auto Consultants Pte Ltd (HQ)



4/22: General View



5/22: General View



6/22: General View

SNC3989X - Submitted by: LKK Auto Consultants Pte Ltd (HQ)



7/22: General View



8/22: General View



9/22: General View

SNC3989X - Submitted by: LKK Auto Consultants Pte Ltd (HQ)



10/22: **General View**



11/22: **General View**



12/22: **General View**

SNC3989X - Submitted by: LKK Auto Consultants Pte Ltd (HQ)



13/22: **General View**



14/22: **General View**




15/22: **General View**

SNC3989X - Submitted by: LKK Auto Consultants Pte Ltd (HQ)



16/22: **General View**



17/22: **General View**



18/22: **General View**

SNC3989X - Submitted by: LKK Auto Consultants Pte Ltd (HQ)



19/22: Reinspection Photo



20/22: Reinspection Photo



21/22: Reinspection Photo

SNC3989X - Submitted by: LKK Auto Consultants Pte Ltd (HQ)



22/22: Reinspection Photo