



# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67597719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

SKX7680J  
TP/FC

NOT ADVISED  
1/1/2008

**M/S :** MS FIRST CAPITAL INSURANCE LTD  
 36 ROBINSON ROAD  
 #16-01 CITY HOUSE  
 SINGAPORE 068877  
**TEL:** 65073848  
**ATTN:** Motor Claim Department

16 days

**Estimate No:** ES2300786/YISHUN  
**Date:** 31 Jul 2023  
**Policy No:** 5118045734-03  
**Veh Reg No:** SKX7680J  
**Make/Model:** MITSUBISHI LANCER  
 1.5 MIVEC GLS 4A/T

**Chassis No:** JMYSRCY2A8U007002  
**Engine No:** 4A910082765  
**Reg. Date:** 28/08/2008

**WS Ref:** TP/FC  
**Claim Type:** Third Party  
**Accident Date:** 29/07/2023  
**TP Veh Reg No:** YP9697A

## Estimate Repair Cost to Vehicle No :SKX7680J

Description	U/Price	Quantity	List Price S\$	Amount S\$
<b>List Price</b>				
1 REAR BUMPER	659.00	1 PC	By 659.00	✓
2 REAR BUMPER LOWER SKIRT	712.00	1 PC	CM 712.00	✓
3 REAR BUMPER REFLECTOR	20.00	2 PC	40.00	✓
4 REAR BUMPER SIDE RETAINER	22.00	2 PC	DIT 44.00	✓
5 REAR BUMPER CLIP	3.50	6 PC	Na 21.00	✓
6 TAILLAMP	266.00	2 PC	532.00	✓
7 TAILLAMP PANEL	88.00	2 PC	By 176.00	✓
8 REAR BOOT	752.00	1 PC	By 752.00	✓
9 REAR BOOT LOGO	41.00	1 PC	Na 41.00	✓
10 REAR BOOT EMBLEM 'ATTRAGE'	20.00	1 PC	Na 20.00	✓
11 REAR BOOT EMBLEM 'MIVEC'	55.00	1 PC	Na 55.00	✓
12 REAR BOOT OUTER MOULDING	336.00	1 PC	CM 336.00	✓
13 REAR BOOT TOP SPOILER	712.00	1 PC	Bu 712.00	✓
14 REAR BOOT INNER LOCK	198.00	1 PC	DIT 198.00	✓
15 REAR BOOT INNER RUBBER	143.00	1 PC	DIT 143.00	502.00
16 REAR BOOT HINGE	185.00	2 PC	By 370.00	✓
17 REAR PANEL	402.00	1 PC	By 402.00	✓
18 REAR PANEL TOP INNER GARNISH	62.00	1 PC	Bu 62.00	✓
19 REAR FENDER	725.00	2 PC	1,450.00	✓
20 REAR FENDER INNER GARNISH	158.00	2 PC	Reform 316.00	✓
21 REAR FENDER INNER GARNISH CLIPS	5.00	3 PC	Na 15.00	✓
22 REAR PANEL AIR GUARD	28.00	1 PC	DIT 28.00	✓
23 REAR EXHAUST PIPE	571.00	1 PC	571.00	?
24 REAR COMPARTMENT PANEL TOP COVER	177.00	1 PC	177.00	?
25 REAR SPARE TYRE COMPARTMENT	980.00	1 PC	By 980.00	✓
			8,812.00	
		Less 10%	881.20	7,930.80
<b>Special Net</b>				
26 REVERSE SENSOR	200.00	1 SET	Na 200.00	✓
27 REAR NUMBER PLATE	35.00	1 PC	By 35.00	✓
28 REVERSE CAMERA	350.00	1 PC	350.00	?
29 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	Na 40.00	✓
			625.00	625.00
<b>Labour</b>				
30 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

**M/S :** MS FIRST CAPITAL INSURANCE LTD  
 36 ROBINSON ROAD  
 #16-01 CITY HOUSE  
 SINGAPORE 068877  
**TEL:** 65073848 **FAX:** 65073849  
**ATTN:** Motor Claim Department

**Estimate No:** ES2300786/YISHUN  
**Date:** 31 Jul 2023  
**Policy No:** 5118045734-03  
**Veh Reg No:** SKX7680J  
**Make/Model:** MITSUBISHI LANCER  
 1.5 MIVEC GLS 4A/T  
**Chassis No:** JMYSRCY2A8U007002  
**Engine No:** 4A910082765  
**Reg. Date:** 28/08/2008

**WS Ref:** TP/FC  
**Claim Type:** Third Party  
**Accident Date:** 29/07/2023  
**TP Veh Reg No:** YP9697A

### Estimate Repair Cost to Vehicle No :SKX7680J

Description	U/Price	Quantity	List Price S\$	Amount S\$
31 REMOVE & REFIX SEAT,CARPET, TOP ROOF LINING ETC	120.00	1 LA	120.00	✓
32 REMOVE & REFIX REAR BUMPER,BOOT, TAILLAMPS; TO CUTTING, WELDING & RENEW REAR BOTH FENDERS, REAR PANEL, REAR COMPARTMENT; TO STRAIGHTEN, KNOCKING & REPAIR REAR BOTH CHASSIS & REALIGN THE SAME	2,800.00	1 LA	2,800.00	2400
33 REMOVE & REFIX REAR RH UNDERCARRIAGE	180.00	1 LA	180.00	✓
34 TO MOUNT ON CAR-O-LINER, TO STRAIGHTEN REAR CHASSIS	250.00	1 LA	250.00	?
35 PUTTY & RESPRAY ON REAR COMPARTMENT, REAR BOTH FENDERS, REAR PANEL, BOOT, HINGES, LOWER SKIRT, SPOILER, CHASSIS & ALL AFFECTED AREAS	1,900.00	1 LA	1,900.00	1700
36 REMOVE & REFIX REVERSE CAMERA, REVERSE SENSOR, SMART KEY SENSOR & RESET SYSTEM	50.00	1 PC	50.00	✓
37 REMOVE & REFIX EXHAUST , CHECK LEAKING & SYSTEM	60.00	1 LA	60.00	✓
38 RUSTPROOFING	90.00	1 LA	90.00	✓
			5,550.00	5,550.00
			<b>Total</b>	<b>S\$ 14,105.80</b>
			Add GST @ 8%	1,128.46
			<b>Total Amount Payable</b>	<b>S\$ 15,234.26</b>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**For Cheng Hoe Motor Pte Ltd**

\_\_\_\_\_  
 AUTHORISED SIGNATURE

# SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of First Submission ..... 29/07/2023 14:18 (SGT)  
Reported by ..... Both Policyholder and Actual Driver  
Date of Accident ..... 29/07/2023 07:25 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... YISHUN AVE 8  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SKX7680J  
INSURED/POLICYHOLDER  
Is company? ..... No  
Name Of Registered Owner ..... ZHANG XINGANG  
NRIC No ..... SXXXX805J  
Email Address ..... zhgxingang@gmail.com  
Mobile Phone No ..... (Phone) +65-92210536  
Alternative Phone No ..... -

### VEHICLE PARTICULARS

Manufacturer ..... Mitsubishi  
Model ..... ATTRAGE 1.2 CVT  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 1193

### INSURANCE COMPANY

Name of Insurance Company ..... Income Insurance Limited  
Policy Number / Cover Note Number ..... 5118045734-03

### DRIVER

Name of Driver ..... ZHANG XINGANG  
NRIC No ..... SXXXX805J  
Date Of Birth ..... 10/02/1981  
Occupation ..... Indoor


Describe Circumstance of the Accident

\*\* NOTE PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.

- ( ) Claim Own Policy      (  ) Claim Third party      ( ) Reporting Onlly
- ( ) Claim OD/ TP at other workshop ( \_\_\_\_\_ )

Sketch Plan

DoA = 29/7/23 @ 7:25am



While approaching the above junction, traffic turned amber to red and I came to a stop. Suddenly vehicle B hit onto the rear of my car. No one was injured.

Declaration

I/We declare the foregoing particulars are true in every respect.

 29/7.9.42am  
 Policyholder's Signature / Date & Time

\_\_\_\_\_  
 Driver's Signature (if driver is not the policyholder) / Date & Time

 29/7  
 Witnessed by Reporting Centre Personnel  
 (Name as in NIC/ID card)  
 (YS)