



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : HSBC LIFE (SINGAPORE) PTE LTD

3/8/2023

### Survey Details:

Date of loss	27-Jul-23
Date of appointment	2-Aug-23
Date of survey	2-Aug-23
Location of survey	BIKE DYNAMIC CENTRE

### Vehicle Details:

Claim Type:	Third Party Claim
Vehicle number	FBR 5934D
Make and Model	YAMAHA NMAX
Date of registration	28/2/2022
Excess	
Market Value	\$ 15,000.00
Part Rebate	\$ 7,980.00
Nett Loss	\$ 7,020.00

### Repair details:

Initial Estimate	\$ -
------------------	------

### Proposed/Revised repair cost:

Parts	
Check items (estimate)	
Labour	
<b>Total</b>	\$ -
<b>Lump Sum(if applicable)</b>	

<b>Number of days for repair</b>	<u>5</u>
----------------------------------	----------



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

*No GIA Report provided. The estimate repair cost of the damaged vehicle is in the region of \$3,500.00 - \$4,500.00.*

**Mandate:**

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
<b>Proposed Total</b>	<b>#VALUE!</b>	