

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURA	NCE BHD	-	Ref:	CS3/LPC23006499/Tny3e2-1	
	300 BEACH ROAD #17-04/07 THE CO) NCOURSESINGAPORE 199555		Date:	04/08/2023	
				Code:	LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKZ 939A	Veh. Inspected		SLB 7161U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/23/23/VP05/027601	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		02/08/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA ALTIS	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	MR053REH104547888	Colour		WHITE	
	Odometer	158320 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	TRIANGLE		6 mm	
	L/H Front Tyre	205/55 R16	TRIANGLE		6 mm	
	R/H Rear Tyre	205/55 R16	TRIANGLE		6 mm	
	L/H Rear Tyre	205/55 R16	TRIANGLE		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	23/06/2023	Inspection Date	е	04/07/2023	
	Survey held at	ECLIPSE AUTO PTE LTD				
		155 KAKI BUKIT AVENUE 1 #01 □00 SHUN LI INDUSTRIAL PARK SINGAPORE 416012				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					