



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|  |  |  |                                  |
|--|--|--|----------------------------------|
| Affiliated to Federation Internationale Des Experts En Automobile  |  | CS3/LPC23006499/Tny3-1   |                                  |
| LONPAC INSURANCE BHD<br>300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555  |  | Ref: <del>CS3/LPC23006499/y3</del><br>Date: <del>27/06/2023</del> 02/08/2023<br>Code: LPC2 |                                  |
| <b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>  |  |  |                                  |
| Insured Veh.   | SKZ 939A   | Veh. Inspected   | SLB 7161U                        |
| Policy No.   |  | Coverage (\$)  | 0.00                             |
| Claim No.  |  | Excess (\$)  | 0.00                             |
| Assign From  | GERALD POH   | Assign Date  | <del>27/06/2023</del> 02/08/2023 |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |  |                                  |
| Make & Model   |  | c.c  | 0                                |
| Engine No.   | HIDDEN   | Year of Reg.   |                                  |
| Chassis No.  |  | Colour   |                                  |
| Odometer   | -  | Steering   |                                  |
| Brakes   |  | Modification   |                                  |
| General  |  |  |                                  |
| <b>3. Conditions of Tyres</b>  |  |  |                                  |
|  | Size   | Make   | Balance                          |
| R/H Front Tyre   |  |  | mm                               |
| L/H Front Tyre   |  |  | mm                               |
| R/H Rear Tyre  |  |  | mm                               |
| L/H Rear Tyre  |  |  | mm                               |
| <b>4. Description of Damages</b>   |  |  |                                  |
|  |  |  |                                  |
| <b>5. General Information</b>  |  |  |                                  |
| Accident Date  | 23/06/2023   | Inspection Date  |                                  |
| Survey held at   | ECLIPSE AUTO PTE LTD<br>155 KAKI BUKIT AVENUE 1<br>#01-00 SHUN LI INDUSTRIAL PARK SINGAPORE 416012 |  |                                  |
| <b>5a. Remarks</b>   |  |  |                                  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |  |  |                                  |