

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
	EQ INSURANCE C	OMPANY LTD	Ref:	CS3/EQI23007837/Tvy3
	5 MAXWELL ROAD #17-00 TOWER BL MND COMPLEXSI	OCK	Date:	02/08/2023
	201111 22/101	110/ III 0112 000 1 10	Code:	EQI
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	YQ 3527S	Veh. Inspected	SMU 740H
	Policy No.		Coverage (\$)	0.00
	Claim No.	DM23HO01592/JS	Excess (\$)	0.00
	Assign From	NEO JIE SI	Assign Date	02/08/2023
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.	Description of Damages			
5.	General Information			
	Accident Date	25/07/2023	Inspection Date	02/08/2023
	Survey held at	MAGNUS GARAGE PTE LTD		
		8 KAKI BUKIT AVENUE 4, #02-24		
		#02-24		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.			
	B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.			
	THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			