

ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	16:20 HRS
ACCIDENT DATE	01-Aug-23
BUS CAPTAIN NAME	MUHAMMAD HAFIZ BIN EKSAN
THIRD PARTY CLAIM AGAINST	MS First Capital

BUS REGISTRATION NUMBER	SG5749D
BUS TYPE (SD/DD)	DD
BUS ROUTE NO.	
BUS ADVERT (Y/N)	N

SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	OS FRONT BATTERY BOX DOOR	1	\$ 550.00
2	OS FRONT BATTERY BOX DOOR FRAME	1	\$ 704.00
3	OS FRONT WHEELARCH PANEL	1	\$ 330.00
4	OS FRONT WHEELARCH TRIM	1	\$ 114.40
5	DOOR LOCK	2	\$ 110.00
6	DOOR HINGE RH	1	\$ 143.00
7	DOOR HINGE LH	1	\$ 132.00
8	GAS SPRING 200N-084670	2	\$ 132.00
9	STOPPER	2	\$ 22.00
10	BATTERY DOOR STICKER	1	\$ 22.00
		8% GST	\$ 180.75
		PARTS TOTAL COST	\$ 2,440.15

SECTION 2 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE :- <ul style="list-style-type: none"> DISMANTLE AND REPLACE ITEM NO: 1 - 10 	\$ 3,250.00
TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS :- <ul style="list-style-type: none"> OS FRONT LAMP COVER OS FRONT BATTERY DOOR OS FRONT PANEL ABOVE BATTERY DOOR OS FRONT WHEELARCH PANEL OS FRONT BODY PANEL OS FRONT CORNER DOME 	\$ 4,550.00
SPRAY PAINTING :- <ul style="list-style-type: none"> OS FRONT LAMP COVER OS FRONT BATTERY DOOR OS FRONT PANEL ABOVE BATTERY DOOR OS FRONT WHEELARCH PANEL OS FRONT BODY PANEL OS FRONT CORNER DOME 	\$ 3,840.00
SPRAY PAINTING \$640 PER PANEL	8% GST
LABOUR CHARGES \$650 PER DAY	LABOUR TOTAL COST
	\$ 931.20
	\$ 12,571.20

ESTIMATED ACCIDENT REPAIR COST



SECTION 3 : RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

SECTION 4 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

		DATE IN	01-Aug-23
		DATE & TIME SURVEY	
		DATE OUT	
BUS TYPE (SD / DD)	DD	TOTAL NUMBER OF DAYS	5
LOSS OF USE COST			\$2,000.00

SUMMARY	
SECTION NO.	COST
1	\$ 2,440.15
2	\$ 12,571.20
3	-
4	\$ 2,000.00
TOTAL	\$ 17,011.35