

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / IP / RES / OD RES / EVA / INV / MV

To in: _____ Vehicle No: _____

at Work: _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Vek: _____

(Policy Condition)

Remark: Tieveh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SLP4967H

Yr Regn: 2017, June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Mazda 3

1496

Colour: _____

Black

A/C: Insured / Std / NI / NA

Sp. Reading: _____

291420

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JM6BN22A8H0158363

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

205/60R16

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. _____

06

mm

Rear

R/Bal. _____

06

mm

L/Bal. _____

06

mm

L/Bal. _____

06

mm

D.O.A. _____

D.O.I. _____

10/06/24

Survey held at

Xin Hng.

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP INC

COE Expiry

Estimate given during: Yes ✓
1st Survey: No C

MV:

PV:

Nett:

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Inve-rs

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Others

Report Format:

Report Format: _____