



Your Ref: 23/24/24/VP02/398424

Date: 21st Aug 2024

Our Ref: CS1/LPM24080171/Enh3e2

M/s Lonpac Insurance Bhd

21st Flr, Bangunan Public Bank
No. 6 Jalan Sultan Sulaiman
50000 Kuala Lumpur, Malaysia
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMG 6201G
INSURED VEHICLE: JRT 9597
ACCIDENT DATE: 01/01/2024**

We thank you for your instruction on 08/08/2024.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMG 6201G from M/s WG Appraisal Services.
- b) Final Repair Bill of SMG 6201G from M/s Speedwerkz Pte Ltd.
- c) Police Report of Vehicles SMG 6201G and JRT 9597.
- d) Colour damaged vehicle photographs of SMG 6201G.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMG 6201G
Make & Model	: KIA Cerato 1.6 (A) EX
Year of Registration	: 2018
Chassis Number	: KNAF3416MK5022830
Engine Capacity	: 1591 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.