

ASS. REC. BY:

REF: LPC1Kenneth**ASSIGNMENT**

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 877K

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 04 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMG 11608Yr Regn: 01.19Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Honda CivicC.G. 1587Colour: M. Black

A/C: Insured / Std / NI / NA

Sp. Reading: 105878

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: NR14FC5650J7002077Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI / S/Rlm / STD / Rlm or

Tyre Size: F: \_\_\_\_\_

R: 225/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 8 mmL/Bal. 6 mmL/Bal. 8 mmD.O.A. 11/8/24D.O.I. 13/8/2024

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐

: Site Insp (\$

) \$ + RS. \$

☐

: Interview (\$

) Photos

☐

Tech Invs (\$

) Others

☐

Weekend (\$

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_



## TSR AUTOMOTIVE PTE LTD

HANDPHONE 93825367

Date : 12 Aug 2024

QUOTATION - THIRD PARTY CLAIM

LONPAC INSURANCE

CLAIM : THIRD PARTY CLAIM

DATE ACCIDENT : 7 Mar 2024

VEH. No : SMG 1160 Z

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : ERGO INSURANCE

| QTY                              | ITEM | AMOUNT | CONDITION |
|----------------------------------|------|--------|-----------|
| Third party vehicle : SLZ 4525 Y |      |        |           |

|   |                           |             |   |
|---|---------------------------|-------------|---|
| 1 | HEADLAMP RH               | \$ 1,985.00 | 7 |
| 2 | HEADLAMP LOWER BRACKET RH | \$ 220.00   | X |
| 1 | FRONT FENDER RH           | \$ 598.00   | X |
| 1 | FRONT FENDER LAMP RH      | \$ 280.00   | X |
| 1 | FOG LAMP OUTER GARNISH RH | \$ 323.00   | ✓ |

TOTAL PARTS : \$ 3,406.00  
 LESS 20% \$ 681.20  
**TOTAL LIST PARTS : \$ 2,724.80**

**S/NETT PARTS**

|   |                            |             |   |
|---|----------------------------|-------------|---|
| 1 | FRONT BUMPER ( SPORT )     | \$ 2,000.00 | ✓ |
| 1 | FRONT BUMPER LOWER GARNISH | \$ 800.00   | ✓ |
| 1 | FRONT RIM RH               | \$ 900.00   | X |

TOTAL S/N : \$ 3,700.00

TOTAL PARTS PRICE : \$ 6,424.80

|                        |             |
|------------------------|-------------|
| AMOUNT BRING FORWARD : | \$ 6,424.80 |
|------------------------|-------------|

Labour charges

\$ 1,000.00 300/

Anti rust

\$ 120.00 X

Check wiring system for lamp etc

\$ 120.00 20/

To do spray painting on accident area

\$ 1,000.00 400/

TOTAL LABOUR :

\$ 2,240.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

GRAND TOTAL PARTS &amp; LABOUR :

\$ 8,664.80

Acknowledged by Repairer

Signature:

Date: