

ASS. REC. BY:

REF:

LPC1

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMG 11608

Yr Regn:

01.19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

C.G

1587

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

105878

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR14PC5650J7002077

Gen. Cohd: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

R:

225/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/8/24

Rear

R/Bal.

8

mm

L/Bal.

8

mm

D.O.I.

13/8/2024

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

O/S / Rm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

TSR AUTOMOTIVE PTE LTD

HANDPHONE 93825367

Date : 12 Aug 2024

QUOTATION - THIRD PARTY CLAIM

LONPAC INSURANCE

CLAIM : THIRD PARTY CLAIM

DATE ACCIDENT : 7 Mar 2024

VEH. No : SMG 1160 Z

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : ERGO INSURANCE

Not Withheld
6/1/24
Murray After Repair
4 days

QTY	ITEM	AMOUNT	CONDITION
Third party vehicle : SLZ 4525 Y			

1	HEADLAMP RH	\$ 1,985.00	7
2	HEADLAMP LOWER BRACKET RH	\$ 220.00	X
1	FRONT FENDER RH	\$ 598.00	X
1	FRONT FENDER LAMP RH	\$ 280.00	X
1	FOG LAMP OUTER GARNISH RH	\$ 323.00	✓

TOTAL PARTS : \$ 3,406.00
LESS 20% \$ 681.20
TOTAL LIST PARTS : \$ 2,724.80

S/NETT PARTS

1	FRONT BUMPER (SPORT)	\$ 2,000.00	✓
1	FRONT BUMPER LOWER GARNISH	\$ 800.00	✓
1	FRONT RIM RH	\$ 900.00	X

TOTAL S/N : \$ 3,700.00

TOTAL PARTS PRICE : \$ 6,424.80

AMOUNT BRING FORWARD :

Labour charges	\$ 1,000.00	300/
Anti rust	\$ 120.00	X
Check wiring system forcus lamp etc	\$ 120.00	20/
To do spray painting on accident area	\$ 1,000.00	400/

TOTAL LABOUR :

\$ 2,240.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

GRAND TOTAL PARTS & LABOUR :

\$ 8,664.80

Acknowledged by Repairer

Signature:

Date: