



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24080201/Avh3m4
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	15/11/2024
SINGAPORE 048583	Code:	LIP

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNA 2780Y	Veh. Inspected	SGY 800T
Policy No.	-	Coverage	0
Claim No.	BVS24/0565	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	13/08/2024

### 2. Vehicle Details

Make & Model	HONDA SHUTTLE	C.C	1496
Engine No.	L15B3534862	Year of Reg.	26/05/2017
Chassis No.	GK81004114	Colour	GREY
Odometer	83905 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/60R15	BRIDGESTONE	6
L/H Front Tyre	185/60R15	BRIDGESTONE	6
R/H Rear Tyre	185/60R15	BRIDGESTONE	6
L/H Rear Tyre	185/60R15	BRIDGESTONE	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	08/08/2024	Inspection Date	14/08/2024
Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days