

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305600723
Date : 16.08.2024

FINALIZATION FORM

To : LKK

Fax :

Attn : STEVE CHEN

Vehicle Reg No. : SH 8808S

Date of Accident : 13.08.2024

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- YQ3505E
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges (include advertisement stickers etc,if any)
 - Total for Part-By-Part Repair Cost**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$1,250.00
Final Lumpsum Repair cost \$1,250.00
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 

Signature : _____

Name : LIM T S

Name : STEVE

Tel : 62148398

Date : _____

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	---	--		
4. LTA Search Fee / GEARS	\$27.25 / \$2.18	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

