



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: JULIE

Ref: CS/INC24080211/Aqh3e2(N)

Date: 22/01/2025

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNJ 9769M	Veh. Inspected	SJV 4316D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1290481-001	Excess (\$)	0.00
Assign From	JULIE	Assign Date	14/08/2024

#### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH	c.c	1987
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JTDGJ20W905001999	Colour	WHITE
Odometer	236765 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm
L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.  
DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	08/08/2024	Inspect Date / Time	26/08/2024 ( 12:21 PM )
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------