

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12/14 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 97800322
LIM KOK WENG
BLK 237 COMPASSVALE WALK
#12-524
SINGAPORE 540237
TEL : FAX :
PH : 97800322
ATTN :

ESTIMATE BILL

Number : EB00006536
Date : 14/06/2024
Case No : AD00014852
Vehicle No : SBQ2688P
Chassis: MR053REH104540792
Year of Mfr 2015
Policy No 5127506688-01
Model : TOYOTA COROLLA
ALTIS 1.6 A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	BOOTLID	1.0	1,294.10	25	970.58
2	BOOTLID HINGE LH	1.0	94.80	25	71.10
3	BOOTLID HINGE RH	1.0	94.80	25	71.10
4	BOOTLID INNER TRIMBOARD	1.0	494.30	25	370.73
5	BOOTLID RUBBER	1.0	238.20	25	178.65
6	BOOTLID LOCK	1.0	542.40	25	406.80
7	BOOTLID CABLE	1.0	105.30	25	78.98
8	BOOTLID LAMP RH	1.0	521.80	25	391.35
9	BOOTLID LAMP LH	1.0	521.80	25	391.35
10	BOOTLID OUTER CHROME	1.0	330.80	25	248.10
11	BOOTLID EMBLEM	1.0	64.90	25	48.68
12	BOOTLID LOGO - COROLLA	1.0	55.70	25	41.78
13	BOOTLID LOGO - ALTIS	1.0	62.00	25	46.50
14	BOOTLID LOCK COVER	1.0		25	
15	BOOTLID LOWER LOCK	1.0	20.90	25	15.68
16	END PANEL	1.0	1,008.40	25	756.30
17	END PANEL TOP GARNISH	1.0	327.80	25	245.85
18	SPARE TYRE PANEL	1.0	1,222.30	25	916.73
19	SPARE TYRE PANEL TOP TRIMBOARD	1.0	362.20	25	271.65
20	REAR FLOOR PANEL SIDE PANEL RH	1.0	37.80	25	28.35
21	REAR FLOOR PANEL SIDE PANEL LH	1.0	37.80	25	28.35
22	SPARE TYRE SCREW	1.0	32.90	25	24.68
23	SPARE TYRE BRACKET	1.0		25	
24	TAIL LAMP RH	1.0	510.80	25	383.10
25	TAIL LAMP LH	1.0	510.80	25	383.10
26	TAIL LAMP CLIP RH	1.0	5.50	25	4.13
27	TAIL LAMP CLIP LH	1.0	5.50	25	4.13
28	TAIL LAMP PANEL LH	1.0	151.30	25	113.48
29	TAIL LAMP PANEL RH	1.0	151.30	25	113.48
30	REAR FENDER LH	1.0	1,715.20	25	1,286.40
31	REAR FENDER RH	1.0	1,715.20	25	1,286.40
32	REAR FENDER INNER TRIMBOARD RH	1.0	447.70	25	335.78
33	REAR FENDER INNER TRIMBOARD LH	1.0	447.70	25	335.78
34	REAR FENDER INNER AIR DUST RH	1.0	185.70	25	139.28

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12/14 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 97800322
LIM KOK WENG
BLK 237 COMPASSVALE WALK
#12-524
SINGAPORE 540237
TEL : FAX :
PH : 97800322
ATTN :

ESTIMATE BILL

Number : EB00006536
Date : 14/06/2024
Case No : AD00014852
Vehicle No : SBQ2688P
Chassis: MR053REH104540792
Year of Mfr 2015
Policy No 5127506688-01
Model : TOYOTA COROLLA
ALTIS 1.6 A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
35	REAR FENDER INNER AIR DUST LH	1.0	185.70	25	139.28
36	REAR FENDER INNER SHIELD RH	1.0	74.80	25	56.10
37	REAR FENDER INNER SHIELD LH	1.0	74.80	25	56.10
38	REAR WINDSCREEN MOULDING	1.0		25	
39	REAR BUMPER	1.0	828.80	25	621.60
40	REAR BUMPER RETAINER RH	2.0	164.40	25	246.60
41	REAR BUMPER RETAINER LH	2.0	164.40	25	246.60
42	REAR BUMPER BRACKET RH	1.0		25	
43	REAR BUMPER BRACKET LH	1.0		25	
44	REAR BUMPER REINFORCEMENT	1.0	598.20	25	448.65
45	REAR BUMPER SPONGE	1.0		25	
46	REAR BUMPER REFLECTOR RH	1.0	81.80	25	61.35
47	REAR BUMPER REFLECTOR LH	1.0	81.80	25	61.35
48	REAR CHASSIS RH	1.0		25	
49	REAR CHASSIS LH	1.0		25	
50	REAR NUMBER LAMP RH	1.0	89.20	25	66.90
51	REAR NUMBER LAMP LH	1.0	89.20	25	66.90
52	REAR DOOR RH	1.0	1,864.60	25	1,398.45
53	REAR DOOR LH	1.0	1,864.60	25	1,398.45
54	REAR FENDER MUDFLAP LH	1.0	71.60	25	53.70
55	REAR FENDER MUDFLAP RH	1.0	71.60	25	53.70
56	REAR REMOTE CENTER LOCK SENSOR	1.0		25	
List Price - Parts Sub Total					14,964.08
57	REAR NUMBER PLATE	1.0	35.00	0	35.00
58	REAR NUMBER PLATE HOLDER	1.0	35.00	0	35.00
59	WINDSCREEN SEALANT	2.0	30.00	0	60.00
60	REVERSE CAMERA	1.0	650.00	0	650.00
61	REVERSE SENSOR	1.0	350.00	0	350.00
Special Nett Price - Parts Sub Total					1,130.00
Parts Total					16,094.08
62	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	2,500.00	0	2,500.00
63	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,800.00	0	1,800.00
64	ANTI-RUST COATING	1.0	300.00	0	300.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12/14 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 97800322
LIM KOK WENG
BLK 237 COMPASSVALE WALK
#12-524
SINGAPORE 540237
TEL : FAX :
PH : 97800322
ATTN :

ESTIMATE BILL

Number : EB00006536
Date : 14/06/2024
Case No : AD00014852
Vehicle No : SBQ2688P
Chassis: MR053REH104540792
Year of Mfr 2015
Policy No 5127506688-01
Model : TOYOTA COROLLA
ALTIS 1.6 A

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
65	WIRING	1.0	100.00	0	100.00
66	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
67	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
68	TO REMOVE & REFIT CUSHION & UPHOSTERY	1.0	200.00	0	200.00
69	TO REMOVE & REFIT FUEL TANK	1.0	250.00	0	250.00
70	FOUR WHEEL ALIGNMENT	1.0	180.00	0	180.00
	Labour 1 Sub Total				5,660.00
SINGAPORE DOLLARS : TWENTY-THREE THOUSAND SEVEN HUNDRED ELEVEN AND CENTS NINETY-FIVE ONLY			Less Excess		0.00
			SUBTOTAL		21,754.08
			GST 9.00%		1,957.87
			TOTAL		23,711.95

Date of accident : 12/06/2024 11:55 AM. Place : PIE TOWARDS JURONG

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	13/06/2024 12:00 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	12/06/2024 11:55 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	PIE TOWARDS JURONG
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBQ2688P
-----------------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LIM KOK WENG
NRIC No	SXXXX421E
Email Address	explorergmt@gmail.com
Mobile Phone No	(Phone) +65-97800322
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1598

INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5127506688-02

DRIVER

Name of Driver	LIM KOK WENG
NRIC No	SXXXX421E
Date Of Birth	15/11/1961
Occupation	Outdoor

Driving Pass Date	24/11/1983
Driving experience	40 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97800322
Alt. Phone Number	-
Email Address	explorergmt@gmail.com
Address	237 COMPASSVALE WALK # 12-524
Address complement	-
Postcode	540237
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	YAP BEE BEE
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 12/06/2024 AT ABOUT 1155HRS, WHILE I WAS DRIVING TOYOTA ALTIS BLUE IN COLOR BEARING REGISTRATION NUMBER: SBQ2688P, WITH MY WIFE ALONG PIE IN THE THIRD LANE, A VAN WHITE IN COLOR BEARING NUMBER: GY6252K, THAT WAS IN FRONT OF ME SLOW DOWN AND NEARLY CAME TO A STOP AS SUCH I HAD TO PRESS MY BRAKE TO PREVENT COLLISION. AS I THEN STARTED TO MOVE OFF SLOWLY WHEN THE FRONT VAN MOVE SLOWLY, A VEHICLE RANGE ROVER, WHITE IN COLOR BEARING REGISTRATION NUMBER: SJJ1516B HAD COLLIDED ONTO MY REAR CAUSING A CHAIN COLLISION BETWEEN MY CAR, THE SAID RANGE ROVER AND ANOTHER BLACK MOTORCAR. I THEN WENT OUT TO MAKE A CHECK AND DISCOVERED THAT THE REAR BOOT WAS DENTED BUT NO DAMAGE TO THE SAID RANGE ROVER.

FURTHERMORE, BOTH MY WIFE AND I WERE NOT INJURED. I HAD EXCHANGE PARTICULARS WITH A MALE INDIAN WHO WAS DRIVING THE RANGE ROVER BUT DID NOT SEE THE DAMAGE OR EXCHANGE PARTICULARS WITH THE OTHER BLACK CAR THAT HAD COLLIDED ONTO THE RANGE ROVER. NO POLICE OR AMBULANCE CAME. I HAD LEFT THE SCENE ONCE I HAD DONE WITH THE SAID INDIAN MAN. I WISH TO STATE THAT THE SAID WHITE VAN THAT WAS EARLIER IN FRONT OF ME WAS THE CAUSE OF THE CHAIN COLLISION.

I AM LODGING THIS REPORT FOR MY INSURANCE CLAIM

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? Yes
 Reasons for not uploading a video of the accident CANNOT LOADING

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJJ1516B
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Private car
 Name of Driver B GURUMURTHY
 NRIC No SXXXX117J
 Contact Number (Phone) +65-96674058
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage -
 Details of property damaged in accident -
 No. Of Passenger (Including Driver) 1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SMK9864C
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Private car
 Name of Driver -
 Contact Number -
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage -
 Details of property damaged in accident -
 No. Of Passenger (Including Driver) 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



[Handwritten signature]

[Handwritten signature] 130624/1146hrs

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan

VECA = SBB 2688 P

VECB = STJ 1516 B

VECC = JMK 9864 C

PIE Towards Turong

vJun2022

1

Describe Circumstance of the Accident

REFER TO GIA REPORT

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated time-frame from the day of occurrence.

Reporting Only


Claim OD

✓ Claim TP

Claim OD/TP at other workshop

Declaration

I/We declare the foregoing particulars are true in every respect.

 130624 1145HRS

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder)
/ Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)



**SINGAPORE
POLICE FORCE**



F/20240613/2030

1 of 2

POLICE REPORT (NP299)

Report No. F/20240613/2030

Police Station Of Origin
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

Date/Time Report Made 13/06/2024 09:50	Vide Report No.	Station Diary No. 26		
Name Of Informant LIM KOK WENG	Address 237 COMPASSVALE WALK #12-524 SINGAPORE 540237			
ID Type / ID No. NRIC NO / S1485421E	Contact No. Home/Office	Mobile 97800322		
Nationality	Email Address			
Occupation Retiree	Sex Male	Age 62	Date of Birth 15/11/1961	Race Chinese
Institution/School Name	Language English			
Date/Time Of Incident 12/06/2024 11:55	Location Of Incident PAN-ISLAND EXPRESSWAY SINGAPORE			

Brief details.

On 12/06/2024 at about 1155hrs, while I was driving Toyota Altis blue in color bearing registration number: SBQ2688P, with my wife along PIE in the third lane, a van white in color bearing number: GY6252K, that was in front of me slow down and nearly came to a stop as such I had to press my brake to prevent collision. As I then started to move off slowly when the front van move slowly, a vehicle Range Rover, white in color bearing registration number: SJJ1516B had collided onto my rear causing a chain collision between my car, the said Range Rover and another black motorcar. I then went out to make a check and discovered that the rear boot was dented but no damage to the said Range Rover.

Signature Of Officer Recording The Report: F / SI NUR YUSMAN BIN ABDUL GHANI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 13/06/2024 09:50
Officer In-Charge Of Case: F / Sengkang N.P.C / SR STAFF SGT LEE JIN WEI Contact No.: 63438999	Classification Of Case:

**SINGAPORE
POLICE FORCE**

F/20240613/2030

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20240613/2030

Furthermore, both my wife and I were not injured. I had exchange particulars with a male Indian who was driving the Range Rover but did not see the damage or exchange particulars with the other black car that had collided onto the Range Rover. No Police or ambulance came. I had left the scene once I had done with the said Indian man. I wish to state that the said white van that was earlier in front of me was the cause of the chain collision.

I am lodging this report for my insurance claim.

Signature Of Officer Recording The Report: F / SI NUR YUSMAN BIN ABDUL GHANI 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 13/06/2024 09:50
Officer In-Charge Of Case: F / Sengkang N.P.C / SR STAFF SGT LEE JIN WEI Contact No.: 63438999	Classification Of Case: