

ASS. REC. BY:

REF:

SMR/

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

I.B.I. %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cohd: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / RIM or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Wkup unable to locate 2nd part, part by part

Date/Time, File Pass to?



: Prell. Report



: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

\$ - RS. \$


F. P. \$

Others

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL



# 方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.  
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

TAN CHENG LIAN  
APT BLK 426 BEDOK NORTH ROAD  
11-503  
SINGAPORE 460426

*Not Notified  
Murray B4pain  
4-5 days*

Dear sir

Estimate cost of repair to vehicle no. SLP6184L

To support

1. Tail gate	1,650.00	?
2. Tail gate rubber	235.00	X
3. Tail gate lock	250.00	X
4. Tail gate damper	280.00	X
5. Tail gate logo	65.00	—
6. Tail gate badge Tucson	65.00	—
7. Tail gate lower garish	268.00	?
8. Rear w/s moulding	158.00	?
9. Rear bumper top	500.00	netts —
10. Rear bumper bottom	350.00	netts —
11. Rear bumper retainer x2	80.00	X
12. Rear bumper sensor x2	632.00	shot
13. Rear bumper reflector x2	220.00	shot
14. Rear bumper reinforcement	350.00	CM
15. Rear bumper bracket x2	120.00	?
16. Rear panel	750.00	?
17. Rear exhaust box	1,350.00	—
18. Rear exhaust centre pipe	1,800.00	—
19. Rear end cater converter	2,985.00	?
Labour charges	208	
Towing	80.00	80
Number plate n holder	80.00	45
Panel beating	980.00	?
Spray painting	900.00	750
To remove and refit w/s ,cushion	250.00	?
Total	14,398.00	

Your faithfully

ALBERT POON

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of First Submission	14/08/2024 14:47 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	13/08/2024 10:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ECP TOWARDS CITY BEFORE BEDOK EXIT
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP6184L
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	TAN CHENG LIAN
NRIC No	SXXXX225C
Email Address	tchenglian@gmail.com
Mobile Phone No	(Phone) +65-98522919
Alternative Phone No	-

## VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Tucson
Variant	HYUNDAI TUCSON 2.0
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2000
Vehicle Fuel	-
First Registration Date	-
Chassis no	-
Effective Date/Time of Ownership	-

## INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5092000288-07

## DRIVER



# SINGAPORE POLICE FORCE



T/20240814/2003

Police Station Of Origin:  
Bedok NPP  
15 Bedok South Road #01-117 SINGAPORE  
460015  
Tel No: 1800-2419999

2 of 3

Report No. T/20240814/2003

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	tan tony	ID No.	S0036716H
Related Vehicle	NIL	Contact No.	98756009
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL
Driver			
Name	TAN CHENG LIAN	ID No.	S7325225C
Related Vehicle	NIL	Contact No.	98522919
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL

### Brief Details.

On 13/08/24 at about 2250hrs i was traveling along ECP towards city before Bedok exit, I was driving on the 1st lane and the 2 cars Infront of me suddenly jam break, and to avoid the accident, i jam break and horned then after I felt a rear bump on my car, and i went down to have a check, and a black police car stopped by and have a check on us. After a while Traffic Police and Ambulance came to the scene. Ambulance conveys a passenger to the hospital, and Traffic Police took my SD card.