

# COMFORTDELGRO ENGINEERING

Sheet1

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road Singapore 579701

Mainline +65 6383 8280  
Facsimile +65 6280 9765

www.cdge.com.sg

Company Registration No: 199500484V

## Workshops

**Braddell**  
205 Braddell Road  
Singapore 579701

**Loyang**  
59 Loyang Drive  
Singapore 508869

**Sin Ming**  
383 Sin Ming Drive  
Singapore 575717

**Pandan**  
45 Pandan Road  
Singapore 608286

**Ubi**  
320 Ubi Road 3  
Singapore 408649

**Senoko**  
24 Senoko Loop  
Singapore 758158

**Sungei Kadut**  
7 Sungei Kadut Way  
Singapore 726791

**Defu**  
6 Defu Avenue 1  
Singapore 639537

**Marymount**  
600 Sin Ming Avenue  
Singapore 575793

Our Ref : 305600811

Date : 15.08.24

Time of Fax : 5

STRIDES / FCAP

Attn : Motor Claims Dept.

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO SHC 831H

- 1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.
- 2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508869 to survey our client's damaged vehicle.
- 3 Enclosed, please find :
  - I) Our Initial estimate of repairs of the damaged vehicle.
  - II) Accident report made by our client.
- 4 I would appreciate it if you could call us to arrange for the survey of the vehicle

~~Shirley Lim~~

Jumari Masudin

Chiang Liat Choon

Lim Tien Siong

Tel no. 62148355 or Hp no. ~~96340011~~

Tel no. 62148315 or Hp no. 96355305

Tel no. 62148314

Tel no. 62148398 or Hp no. 96358546

92966006

- 5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.
- 6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

7 Thank you.

Yours faithfully

for Vice President

Crash Repairs & Claims Recovery

Page 1

A member of

COMFORTDELGRO



CERT. NO: 05-0-0516  
ISS. 150 0301 : 2009

**CITYCAB PTE LTD****REPAIR ESTIMATE\***VEHICLE NO **SHC 831H**DATE **14.08.2024**MAKE **REG. 14.01.2020****CHIANG /STRIDES/FCAP**MODEL **TOYOTA PRIUS G4A**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$551.89
1	REAR BUMPER LOWER COVER			\$654.96
1	REAR BUMPER REINFORCEMENT			\$378.32
10	REAR BUMPER CLIP		\$2.20	\$22.00
1	REAR BUMPER REFLECTOR RH			\$55.00
	<b>SUB TOTAL</b>			<b>\$1,662.17</b>
	<b>25.00%</b>			<b>\$415.54</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$1,246.63</b>
1	REAR BUMPER MAT			\$50.00
1	REAR BUMPER ADVERTISEMENT			\$80.00
2	REAR FENDER ADVERTISEMENT LH/RH		\$100.00	\$200.00
1	REAR REVERSE SENSOR			\$135.70
				<b>\$465.70</b>
	<b>Labour Charge</b>			
	Panel Beating			\$760.00
	Spray Painting Charge			\$350.00
	Remove/Refix Reverse Sensor			\$60.00
	<b>TOTAL LABOUR</b>			<b>\$1,170.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$2,882.32</b>
This is an Initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the Insurance company.				