# LKK

# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

#### **Tax Invoice**

STRIDES PREMIER AUTOMOTIVE SERVICES PL.

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705

INV No.: SAC2400415

INV Date: 28-08-2024

Reference CS/SMR24080245/Enp3m4

Code SMR

**PROFESSIONAL SERVICE FEE** 

Vehicle No. SHC 831H Insured Veh. SHC 4323G

Claim No. TAX/08/24/2047

Policy No.

Accident Date 14/08/2024 Inspection Date 15/08/2024

Description	Amount
Survey Inspection	128.00
Resurvey Inspection	0.00
Digital Photographs	0.00
Transportation	0.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

# **LKK Auto Consultants Pte Ltd**

SML	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Fode actions Interns the	ala Dan Farmanta Fra	Automobile		
	Affiliated to Federation Internationale Des Experts En Automobile					
MS		RAUTOMOTIVE SERVICES PL.	Ref:	CS/SMR24080245/Enp3m4		
	60 WOODLANDS II 757705	NDUSTRIAL PARK E4 SINGAPORE	Date:	28/08/2024		
			Code:	SMR		
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHC 4323G	Veh. Inspected	SHC 831H		
	Policy No.	-	Coverage	0		
	Claim No.	TAX/08/24/2047	Excess	\$0.00		
	Assign From	HUA YEN	Assign Date	15/08/2024		
2.		Vehicle	Details			
	Make & Model	TOYOTA PRIUS	C.C	1798		
	Engine No.	2ZR2G10775	Year of Reg.	14/01/2020		
	Chassis No.	JTDKB3FU003090411	Colour	YELLOW		
	Odometer	629602 KM	Steering	IN ORDER		
	Brakes	IN ORDER	General	FAIR		
	Modification(s)	RIMS: SPORTS RIM				
3.		Condition	s of Tyres			
		Size	Make	Balance (mm)		
	R/H Front Tyre	195/65R15	WEST LAKE	5		
	L/H Front Tyre	195/65R15	WEST LAKE	5		
	R/H Rear Tyre	195/65R15	WEST LAKE	5		
	L/H Rear Tyre	195/65R15	WEST LAKE	5		
4.		Description	of Damages			
THE	VEHICLE SUSTAIN	ED DAMAGES AT THE REAR PORTIC	DN.			
DAM	AGES SEE DETAIL	S.				
5.		General Ir	nformation			
	Accident Date	14/08/2024	Inspection Date	15/08/2024		
	Survey held at	COMFORTDELGRO ENGINEERING 59 LOYANG DRIVE SINGAPORE 508969	PTE LTD			
5a.		Rem	arks			
		AS CONDUCTED ON A"WITHOUT PR YOUR INSTRUCTIONS, WE HAVE N		REPAIRS.		
5b.	5b. Estimate Days of Repair					
	IMATED NORMAL P	ERIOD FOR REPAIR: 2 Working Days				



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

# ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SHC 831H

	REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
1	REAR BUMPER	TO REPAIR SEE LABOUR	\$551.89	\$0.00	
1	REAR BUMPER LOWER COVER	DEFORMED	\$654.96	\$654.96	
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	\$378.32	\$0.00	
10	REAR BUMPER CLIP @\$2.20	NOT NECESSARY	\$22.00	\$0.00	
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	\$55.00	\$0.00	
	LESS 25.00% DISCOUNT		(\$415.54)	(\$163.74)	
			\$1,246.63	\$491.22	

	Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
1	REAR BUMPER MAT (SN)	NOT NECESSARY	\$50.00	\$0.00	
1	REAR BUMPER ADVERTISEMENT (SN)	NECESSARY	\$80.00	\$80.00	
2	REAR FENDER ADVERTISEMENT LH/RH @\$100.00 (SN)	NECESSARY	\$200.00	\$200.00	
1	REAR REVERSE SENSOR (SN)	NOT NECESSARY	\$135.70	\$0.00	
		\$465.70	\$280.00		

Labour			
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER		\$760.00	\$380.00
SPRAY PAINTING CHARGE		\$350.00	\$280.00
REMOVE/REFIX REVERSE SENSOR	NOT NECESSARY	\$60.00	\$0.00
		\$1,170.00	\$660.00

GRAND TOTAL	\$2,882.33	\$1,431.22	
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$1,150.00	
Report Ref No: CS/SMR24080245/Enn3m4			

# CTY

STEVE CHEN TSUE YEE



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.

  2. This Form must be completed by the Policyholder and/or the Actual Driver.

  3. Enformation provided must be as truthful and accurate as possible. Any withit misrepresentation or witholding of material facts may allow insurance companies to reputiate. policy liability.

- posity assists and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

  5. Any false reporting may be referred to the Police for Investigation.

  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the Centred Insurance Association of Bingapure (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforeseld.

# ACCIDENT STATEMENT

Date of First Submission

Reported by Date of Accident

Exact Location of Accident Additional Location Information

Country/State of Loss

15/08/2024 11:48 (SGT)

Actual Driver

14/08/2024 23:00 (SGT)

Orchard Rd, Singapore

**OUTSIDE NGEE ANN CITY** 

Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number

SHC831H

INSUREDIPOLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No **Email Address** 

Mobile Phone No

Alternative Phone No

Yes

CITYCAB PTE LTD

1XXXXX839G

fleetsafety@cdgtaxl.com.sg (Phone) +65-81251686

(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

Transmission CC

Vehicle Fuel

First Regisration Date

Chassis no

Effective Date/Time of Ownership

Toyota Prius

5DR HATCHBACK (AUTO)

Private hire

No - Claiming third party

Taxi Auto 1798

Petrol-Electric

JTDKB3FU003090411

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number MS First Capital Insurance Ltd D-24101860MFCT

DRIVER



Page 1 of 16



Name of Driver
NRIC No
Date Of Birth
Occupation
Driving Pass Date
Driving License Pass Class
Driving License Validity
Driving experience

Gender Mobile Number Alt. Phone Number Email Address

Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident

Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged? Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

Translator's name Translator's ID

Translator's phone number

Translator's email

Original language used in the statement

PASSENGER 1

Name Gender

PASSENGER 2

Name Gender

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given?

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

LEE KOK NGEE SXXXX338G 28/02/1966 Outdoor 19/03/1986

3 Valid

38 YEARS AND 5 MONTHS

Male

(Phone) +65-81251686

fleetsafety@cdgtaxl.com.sg

BLK 733 WOODLANDS CIRCLE #11-95

730733 No

RELIEF DRIVER

No

-

Collision - Head to Rear

Clear Dry

No

2 Yes No

Yes 3

No

-

-

UNKNOWN

Male

UNKNOWN Male

No No

NO

Accident report SA1K248F000A

Page 2 of 16



ON 14/08/2024 AT ABOUT 2300HRS I WAS DRIVING VEHICLE (A) BEARING REGISTRATION NUMBER SHC831H ENROUTE FROM AFTER PICKING UP MY PASSENGERS AT GRAND HYATT HOTEL TO DROP OFF MY PASSENGERS TO MBS CASINO FOR WORK PURPOSES. WHILE DRIVING ALONG LANE 2 OF ORCHARD ROAD OUT SIDE NGEE ANN CITY THE VEHICLES INFRONT OF ME SLOWED DOWN AND I STOPPED I TOO SLOWED DOWN AND STOPPED. AFTER STATIONARY FOR ABOUT 10SECONDS THE FRONT OF VEHICLE (B) BEARING REGISTRATION NUMBER SHC4323G HIT ONTO THE REAR OF MY VEHICLE, I SUSTAINED NECK PAIN AND WILL SEE DOCTOR. MY PASSENGERS ALSO SUSTAINED NECK PAIN AS WELL, AND I TOLD THEM TO CONTACT COMFORTDELGRO.

#### ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Reasons for not uploading a video of the accident

Yes Yes

FILE IS NOT SUITABLE

# DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC4323G Vehicle Manufacturer Toyota

PRIUS HYBRID 1.8 CVT Vehicle Model

Vehicle Variant Vehicle Colour

Vehicle Category Taxi

LIN YI KUAN Name of Driver NRIC No SXXXX658B

Contact Number Address

Address complement Postcode

Insurance Company Name Nature Of Damage

Details of property damaged in accident No. Of Passenger (Including Driver)

## INJURED PERSONS DETAILS

#### INJURED 1

Name of injured person LEE KOK NGEE

Gender

Phone No (Phone) +65-81251686

BLK 733 WOODLANDS CIRCLE #11-95 Address

Address Complement

Post Code 730733 Approximate Age Years Old

Injuries Sustained **NECK PAIN** Injured person in which vehicle? SHC831H

Were seat belts worn? Yes

Was this injured conveyed to hospital by ambulance? No

#### **INJURED 2**

Name of injured person UNKNOWN Male

Gender Phone No Address

Address Complement Post Code

Approximate Age Years Old **NECK PAIN** Injuries Sustained Injured person in which vehicle? SHC831H Yes

Were seat belts worn? Was this injured conveyed to hospital by ambulance? No

INJURED 3

UNKNOWN Name of injured person Male Gender

Accident report SA1K248F000A

Page 3 of 16





#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please correctly report the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any willful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

funderstand, acknowledge, agree and consent that

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) Investigating the accident and/or my claims.
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (Collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents(including their lawyers/law firms), which may be sted outside of Singapore, for one or more of the above Purposes.

POF


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

15/08/2024 0300HRS



Accident report SA1K248F000A

**CS** CamScanner



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**INSPECTION PHOTOS (Page 1 of 5)** 











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**INSPECTION PHOTOS (Page 2 of 5)** 











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**INSPECTION PHOTOS (Page 3 of 5)** 














51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**INSPECTION PHOTOS (Page 4 of 5)** 












51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**INSPECTION PHOTOS (Page 5 of 5)** 













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**REINSPECTION PHOTOS (Page 1 of 1)** 





