

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,

auto	Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
	Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	onale Des Experts En	Automobile		
MS	INCOME INSURANCE LTD		Ref:	CS/INC24080248/Avh3m4		
i	75 BRAS BASAH I		Date:	22/11/2024		
	NCOME CENTRE SINGAPORE 189557		Code:	INC		
1.	. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GZ 6523Z	Veh. Inspected	GBL 2520R		
	Policy No.	-	Coverage	0		
	Claim No.	MT/1290735-001	Excess	\$0.00		
	Assign From	MARCUS XIAO	Assign Date	15/08/2024		
2.	2. Vehicle Details					
	Make & Model	NISSAN NV200	C.C	1597		
	Engine No.	HR16177733D	Year of Reg.	26/04/2021		
	Chassis No.	VM20161700	Colour	GREY		
	Odometer	65579 KM	Steering	IN ORDER		
	Brakes	IN ORDER	General	GOOD		
	Modification(s)	RIMS: NIL				
3.	3. Conditions of Tyres					
		Size	Make	Balance (mm)		
	R/H Front Tyre	175/70R14C	GITI	6		
	L/H Front Tyre	175/70R14C	GITI	6		
	R/H Rear Tyre	175/70R14C	GITI	6		
	L/H Rear Tyre	175/70R14C	GITI	6		
4. Description of Damages						
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.						
DAMAGES SEE DETAILS.						
5.	General Information					
	Accident Date	13/08/2024	Inspection Date	14/08/2024 (18:33)		
	Survey held at	MS CAR AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days