

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	MS FIRST CAPITAL	INSURANCE LTD	Ref:	CS3/FCI24080260/Tnp3e2	
	16 RAFFLES QUAY #42-01 HONG LEON	IC BUILDING	Date:	26/08/2024	
	SINGAPORE 04858		Code:	FCI2	
1.	1. Policy Particulars :- PRE-REPAIR SURVEY				
	Insured Veh.	SHB 4174A	Veh. Inspected	GBL 6182G	
	Policy No.	D-24101861MFCT	Coverage	0	
	Claim No.	D24007048MFCT	Excess	\$0.00	
	Assign From	CAROLINE	Assign Date	15/08/2024	
2. Vehicle Details					
	Make & Model	TOYOTA HIACE	C.C	1998	
	Engine No.	1TR2376726	Year of Reg.	02/12/2021	
	Chassis No.	TRH2000346565	Colour	SILVER	
	Odometer	57297 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: NIL			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	Size 195 R15	Make MICHELIN	Balance (mm) 6	
	R/H Front Tyre L/H Front Tyre			, ,	
		195 R15	MICHELIN	6	
	L/H Front Tyre	195 R15 195 R15	MICHELIN MICHELIN	6	
4.	L/H Front Tyre R/H Rear Tyre	195 R15 195 R15 195 R15	MICHELIN MICHELIN MICHELIN MICHELIN	6 6 6	
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	195 R15 195 R15 195 R15 195 R15	MICHELIN MICHELIN MICHELIN MICHELIN Of Damages	6 6 6 6	
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	195 R15 195 R15 195 R15 195 R15 Description o	MICHELIN MICHELIN MICHELIN MICHELIN DIF Damages N/S PORTION AN	6 6 6 6	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	195 R15 195 R15 195 R15 195 R15 195 R15 Description of DAMAGES AT THE FRONT, FRONT	MICHELIN MICHELIN MICHELIN MICHELIN DIF Damages N/S PORTION AN	6 6 6 6	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINI	195 R15 195 R15 195 R15 195 R15 195 R15 Description of the description	MICHELIN MICHELIN MICHELIN MICHELIN Of Damages N/S PORTION AN Cormation Inspection Date	6 6 6 6 0 UNDERCARRIAGE.	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINI Accident Date	195 R15 195 R15 195 R15 195 R15 195 R15 Description of the second of the	MICHELIN MICHELIN MICHELIN MICHELIN OF Damages N/S PORTION AN Cormation Inspection Date S - 60 JALAN LAM	6 6 6 6 0 UNDERCARRIAGE.	
5a. A) T B) T THE C) E D)M	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINI Accident Date Survey held at HE INSPECTION WAHE REPAIR ESTIMA' REPAIRER WAS TO NCLOSED PLEASE ARKET VALUE:\$82,0	195 R15 195 R15 195 R15 195 R15 195 R15 Description of the properties of the proper	MICHELIN MICHELIN MICHELIN MICHELIN MICHELIN MICHELIN Of Damages N/S PORTION AN Formation Inspection Date S - 60 JALAN LAM MICHELIN MICHELI	6 6 6 6 0 UNDERCARRIAGE. 16/08/2024 (15:29) HUAT, #06-32, CARROS CENTRE,	
5a. A) T B) T THE C) E D)M	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAINI Accident Date Survey held at HE INSPECTION WAHE REPAIR ESTIMA' REPAIRER WAS TO NCLOSED PLEASE ARKET VALUE:\$82,0	195 R15 195 R15 195 R15 195 R15 195 R15 Description of the properties of the proper	MICHELIN MICHELIN MICHELIN MICHELIN MICHELIN Of Damages N/S PORTION AN Formation Inspection Date S - 60 JALAN LAM Arks EJUDICE" BASIS. ME OF INSPECTION APHS. LE IS IN THE REGION LICHARY LE IS IN THE REGION MICHELIN MICH	6 6 6 6 D UNDERCARRIAGE. 16/08/2024 (15:29) HUAT, #06-32, CARROS CENTRE,	

MTH

MOHAMAD TAUFIKH