



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24080261/Uqp3
(BUDGET DIRECT INSURANCE)	Date:	16/08/2024
190 CLEMENCEAU AVENUE #03-01		
SINGAPORE SHOPPING CENTRE SINGAPORE 239924	Code:	AGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLJ 5448P	Veh. Inspected	SLK 1036R
Policy No.	P10119888R05	Coverage	0
Claim No.	C10031097/ML	Excess	\$0.00
Assign From	MAYBIE	Assign Date	16/08/2024

### 2. Vehicle Details

Make & Model	HONDA VEZEL (A)	C.C	1496
Engine No.	L15B4404245	Year of Reg.	05/01/2017
Chassis No.	RU11204245	Colour	SILVER
Odometer	153030 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60R16	YOKOHAMA	6
L/H Front Tyre	215/60R16	YOKOHAMA	6
R/H Rear Tyre	215/60R16	YOKOHAMA	6
L/H Rear Tyre	215/60R16	YOKOHAMA	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	12/08/2024	Inspection Date	20/08/2024
Survey held at	PROFI AUTOMOTIVE BLK 10 KAKI BUKIT ROAD 2 #01-05 FIRST EAST CENTRE SINGAPORE 417868		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days