



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24080266/Kqp3e2
50 RAFFLES PLACE #03-03	Date:	23/08/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM (PHYSICAL REINSPECTION)

Insured Veh.	SNG 3432P	Veh. Inspected	SKR 2346P
Policy No.	D24MTPV01005017	Coverage	0
Claim No.	CMTD2401415/JYC	Excess	\$0.00
Assign From	CHENG JIA YI	Assign Date	16/08/2024

### 2. Vehicle Details

Make & Model	AUDI A6 (A)	C.C	1984
Engine No.	CDN412251	Year of Reg.	27/01/2015
Chassis No.	WAUZZZ4G0EN170424	Colour	METALLIC BLACK
Odometer	179904 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/55R17	MICHELIN	7
L/H Front Tyre	225/55R17	MICHELIN	7
R/H Rear Tyre	225/55R17	MICHELIN	7
L/H Rear Tyre	225/55R17	MICHELIN	7

### 4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.

REPAIR CONDITION SEE DETAILS.

### 5. General Information

Accident Date	20/04/2024	Inspection Date	19/08/2024
Survey held at	MJE MOTOR BLK 7 SIN MING IND EST SEC C #01-96 SINGAPORE 575642		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days