

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	LONPAC INSURANCE BHD		Ref:	CS/LPC24080268/Kvh3e2	
	300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555		Date:	02/09/2024	
	#17-04/07 THE CON	NCOURSE SINGAPORE 199555	Code:	LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 8666X	Veh. Inspected	SKV 1480U	
	Policy No.	-	Coverage	0	
	Claim No.	24/24/24/VC05/029713	Excess	\$0.00	
	Assign From	CHARMAINE KONG	Assign Date	16/08/2024	
2. Vehicle Details					
	Make & Model	TOYOTA ALTIS (A)	C.C	1598	
	Engine No.	1ZRX528693	Year of Reg.	31/08/2015	
	Chassis No.	MR053REH104538005	Colour	METALLIC GREY	
	Odometer	145369 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: STANDARD ALLOY RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	205/55R16	MICHELIN	5	
	L/H Front Tyre	205/55R16	MICHELIN	5	
	R/H Rear Tyre	205/55R16	MICHELIN	8	
	L/H Rear Tyre	205/55R16	MICHELIN	8	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT BODY AND UNDERCARRIAGE.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	ccident Date 15/08/2024 Inspection Date 19/08/2024			
	Survey held at	Burvey held at BLK 5034 ANG MO KIO INDUSTRIAL PARK 2 #01-341 SINGAPORE 569537 - REPAIRER: JD MOTORSPORTS PTE LTD			
5a.	Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Da	ys of Repair		

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days