

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	AUTO & GENERAL	INSURANCE (S) PL	Ref:	CS/AGI24060011/Uqp3e2
	(BUDGET DIRECT I 190 CLEMENCEAU		Date:	10/06/2024
		PING CENTRE SINGAPORE 239924	Code:	AGI
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SNF 1502P	Veh. Inspected	SMQ 6537K
	Policy No.	-	Coverage	0
	Claim No.	C10029841/MC	Excess	\$0.00
	Assign From	MICHAEL	Assign Date	10/06/2024
2. Vehicle Details				
	Make & Model	B.M.W. Z4 SDRIVE (A)	C.C	1998
	Engine No.	13665555B48B20B	Year of Reg.	18/04/2019
	Chassis No.	WBAHF12060WW16199	Colour	BLUE
	Odometer	33484 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3.	. Conditions of Tyres			
		Size	Make	Balance (mm)
İ	R/H Front Tyre	225/45ZR18	MICHELIN	5
1	Torri Torri Tyre			
	L/H Front Tyre	225/45ZR18	MICHELIN	5
	L/H Front Tyre R/H Rear Tyre	225/45ZR18 255/40ZR18	MICHELIN MICHELIN	5 5
	L/H Front Tyre		<b>+</b>	
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	255/40ZR18 255/40ZR18 <b>Description</b> 6	MICHELIN MICHELIN	5
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	255/40ZR18 255/40ZR18	MICHELIN MICHELIN	5
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	255/40ZR18 255/40ZR18  Description of the DAMAGES AT THE O/S BODY.	MICHELIN MICHELIN	5
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  VEHICLE SUSTAIN	255/40ZR18 255/40ZR18  Description of the DAMAGES AT THE O/S BODY.	MICHELIN MICHELIN of Damages	5
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  VEHICLE SUSTAIN	255/40ZR18 255/40ZR18  Description of the DAMAGES AT THE O/S BODY. S.	MICHELIN MICHELIN of Damages	5
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN	255/40ZR18 255/40ZR18  Description of the DAMAGES AT THE O/S BODY.  General Inc.	MICHELIN MICHELIN of Damages  formation Inspection Date	5 5 14/06/2024
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN AGES SEE DETAILS Accident Date	255/40ZR18 255/40ZR18  Description of the DAMAGES AT THE O/S BODY.  S.  General In: 05/06/2024 3021A UBI ROAD 1 #01-42 SINGAPO	MICHELIN MICHELIN of Damages  formation Inspection Date RE 408715-AUTON	5 5 14/06/2024
THE DAM  5.  5a. A) TI	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN AGES SEE DETAILS Accident Date Survey held at	255/40ZR18 255/40ZR18  Description of the DAMAGES AT THE O/S BODY.  S.  General Interpretation of the Damage of th	MICHELIN MICHELIN of Damages  formation Inspection Date RE 408715-AUTON arks EJUDICE" BASIS.	5 5 14/06/2024 IOBILE INTEGRATED

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days