



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24060110/Uvh3e2
75 BRAS BASAH ROAD	Date:	19/07/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 5173K	Veh. Inspected	SNG 269P
Policy No.	-	Coverage	0
Claim No.	MT/1281554-002	Excess	\$0.00
Assign From	EILEEN LEE	Assign Date	18/06/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ E200 (A)	C.C	1991
Engine No.	26492030496348	Year of Reg.	23/06/2022
Chassis No.	W1K2130802B055259	Colour	GREY
Odometer	55309 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/45ZR18	CONTINENTAL	8
L/H Front Tyre	245/45ZR18	CONTINENTAL	8
R/H Rear Tyre	245/45ZR18	CONTINENTAL	8
L/H Rear Tyre	245/45ZR18	CONTINENTAL	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/06/2024	Inspection Date	18/06/2024 (02:31PM)
Survey held at	WE GARAGE - 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days