

REF:

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / ~~TP~~ / TP RES / OD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at W/O _____

of _____

Insured: _____

Policy No: _____

Claim's No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNG6516L Yr Regn: 2020 / Feb.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz GLA 180 C.C. 1595Colour: Black A/C: Insured / Std / NI / NASp. Reading: 88532 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDC1569422J688432Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/50R18R: 235/50R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 20/09/24Survey held at KaryDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRees o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Claim

COE Expiry: _____

Estimate given during: Yes C /1st Survey: No C /MV: 108KPV: 42.7KNett: 65.3K

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Inve (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS: \$ _____

Photos _____

Others _____

Report Forwarded: _____

Reported by: _____