

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internationa	-	
MS	INCOME INSURAN	CE LTD	Ref:	CS/INC24080300/Anh3m4
	75 BRAS BASAH R	OAD SINGAPORE 189557	Date:	25/11/2024
	INCOME CENTRE	SINGAL ONE 109007	Code:	INC
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SLM 8538C	Veh. Inspected	GBG 3852C
	Policy No.	-	Coverage	0
	Claim No.	MT/1291134-002	Excess	\$0.00
	Assign From	YEE PEI LI	Assign Date	20/08/2024
2. Vehicle Details				
	Make & Model	NISSAN NV350	C.C	2488
	Engine No.	YD25416935A	Year of Reg.	31/07/2017
	Chassis No.	JN1MC2E26Z0008114	Colour	SILVER
	Odometer	302428 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: NIL		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	195R15C	TRIANGLE	6
	L/H Front Tyre	195R15C	TRIANGLE	6
		195R15C 195R15C	TRIANGLE TRIANGLE	6
	L/H Front Tyre			
4.	L/H Front Tyre R/H Rear Tyre	195R15C	TRIANGLE TRIANGLE	6
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	195R15C 195R15C	TRIANGLE TRIANGLE of Damages	6
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	195R15C 195R15C Description o ED DAMAGES AT THE REAR PORTIO	TRIANGLE TRIANGLE of Damages	6
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN	195R15C 195R15C Description o ED DAMAGES AT THE REAR PORTIO	TRIANGLE TRIANGLE of Damages N.	6
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN	195R15C 195R15C Description of ED DAMAGES AT THE REAR PORTIO S.	TRIANGLE TRIANGLE of Damages N.	6
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN MAGES SEE DETAIL	195R15C 195R15C Description of ED DAMAGES AT THE REAR PORTION S. General In	TRIANGLE TRIANGLE of Damages N. formation Inspection Date	6 6 20/08/2024 (17:52)
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN AGES SEE DETAIL Accident Date	195R15C 195R15C Description of ED DAMAGES AT THE REAR PORTIO S. General In: 18/08/2024 JL PERFECT AUTOWORK PTE LTD	TRIANGLE TRIANGLE of Damages N. formation Inspection Date EMIER @ KAKI BU	6 6 20/08/2024 (17:52)
THE DAM 5. 5a. A) T	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN AGES SEE DETAIL Accident Date Survey held at	195R15C 195R15C Description of the properties	TRIANGLE TRIANGLE of Damages N. formation Inspection Date EMIER @ KAKI BU arks EJUDICE" BASIS.	6 6 20/08/2024 (17:52) KIT, SINGAPORE 415875

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days