

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

Our Job Ref No : 305601141  
Date : 23.08.2024

## FINALIZATION FORM

To : LKK

Fax :

Attn : STEVE CHEN

Vehicle Reg No. : SH 7823D

Date of Accident : 15.08.2024

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SNA8967L

2. The finalized amount shall be:

(a) Spare Parts after List discount \_\_\_\_\_

(b) Labour Charges (include advertisement stickers etc,if any) \_\_\_\_\_

**Total for Part-By-Part Repair Cost** \_\_\_\_\_

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20% \$4,100.00

**Final Lumpsum Repair cost** \$4,100.00

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : \_\_\_\_\_

Name : LIM T S

Name : STEVE

Tel : 62148398

Date : \_\_\_\_\_

Fax : 65468156

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	---	--		
4. LTA Search Fee / GEARS	\$27.25 / \$2.18	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_