

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internationa	ile Des Experts En	Automobile
MS	LIBERTY INSURANCE PTE LTD		Ref:	CS/LIP24060114/Uqh3m4
		JAY #25-01 NORTH TOWER	Date:	18/06/2024
	SINGAPORE 0485	83	Code:	LIP
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SCV 1162H	Veh. Inspected	SLU 5774P
	Policy No.	-	Coverage	0
	Claim No.	IVS24/0833	Excess	\$0.00
	Assign From	ANDY SEAH	Assign Date	18/06/2024
2.	Vehicle Details			
	Make & Model	HYUNDAI ELANTRA AD 1.6 GLS AT	C.C	1591
	Engine No.	G4FGHU830768	Year of Reg.	07/12/2017
	Chassis No.	KMHD841CMJU591142	Colour	SILVER
	Odometer	65953 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3.		Conditions of Tyres		
		Size	Make	Balance (mm)
	R/H Front Tyre	195/65R15	YOKOHAMA	6
	L/H Front Tyre	195/65R15	YOKOHAMA	6
	R/H Rear Tyre	195/65R15	YOKOHAMA	6
	<u> </u>			
	L/H Rear Tyre	195/65R15	YOKOHAMA	6
4.	L/H Rear Tyre	Description (YOKOHAMA of Damages	6
	L/H Rear Tyre		YOKOHAMA of Damages	6
THE	L/H Rear Tyre	Description of the DAMAGES AT THE O/S FRONT PO	YOKOHAMA of Damages	6
THE	L/H Rear Tyre VEHICLE SUSTAIN	Description of the DAMAGES AT THE O/S FRONT PO	YOKOHAMA of Damages DRTION.	6
THE DAM	L/H Rear Tyre VEHICLE SUSTAIN	Description of the DAMAGES AT THE O/S FRONT POLS.	YOKOHAMA of Damages DRTION.	19/06/2024
THE DAM	L/H Rear Tyre VEHICLE SUSTAIN MAGES SEE DETAIL	Description of NED DAMAGES AT THE O/S FRONT POLS. General In	YOKOHAMA of Damages DRTION. formation Inspection Date	19/06/2024
THE DAM	L/H Rear Tyre VEHICLE SUSTAIN AGES SEE DETAIL Accident Date	Description of NED DAMAGES AT THE O/S FRONT POLS. General In: 30/04/2024 FALCON-AIR AUTO SERVICES PTE I	YOKOHAMA of Damages DRTION. formation Inspection Date LTD SINGAPORE 52884	19/06/2024
THE DAM 5. 5a. A) T	L/H Rear Tyre VEHICLE SUSTAIN MAGES SEE DETAIL Accident Date Survey held at HE INSPECTION W	Description of NED DAMAGES AT THE O/S FRONT POLS. General In: 30/04/2024 FALCON-AIR AUTO SERVICES PTE I BLK 9006 TAMPINES ST 93 #01-200 S	YOKOHAMA of Damages ORTION. formation Inspection Date LTD SINGAPORE 52884 arks EJUDICE" BASIS.	19/06/2024

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days