

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	AUTO & GENERAL	INSURANCE (S) PL	Ref:	CS/AGI24080316/Knp3e2	
	BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01		Date:	20/08/2024	
		PING CENTRE SINGAPORE 239924	Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMH 9933C	Veh. Inspected	SGK 1512S	
	Policy No.	-	Coverage	0	
	Claim No.	C10031208 / KC	Excess	\$0.00	
	Assign From	LAN BOON CHIN	Assign Date	20/08/2024	
2. Vehicle Details					
	Make & Model	HONDA CRV (A)	C.C	1498	
	Engine No.	L15BG2221015	Year of Reg.	10/01/2020	
	Chassis No.	MRHRW1880KP000034	Colour	GREY	
	Odometer	93357 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: STANDARD ALLOY RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	235/60R18	MICHELIN	8	
	L/H Front Tyre	235/60R18	MICHELIN	8	
	R/H Rear Tyre	235/60R18	MICHELIN	7	
	L/H Rear Tyre	235/60R18	MICHELIN	7	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	17/08/2024	Inspection Date	20/08/2024	
	Survey held at	TSR AUTOMOTIVE PTE LTD			
		160 SIN MING DRIVE #06-01 SIN MING AUTOCITY			
		SINGAPORE 575722			
5a.					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days