



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24080325/Aqp3e2
(BUDGET DIRECT INSURANCE)	Date:	23/12/2024
190 CLEMENCEAU AVENUE #03-01		
SINGAPORE SHOPPING CENTRE SINGAPORE 239924	Code:	AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SBZ 981H	Veh. Inspected	SJU 5725E
Policy No.	-	Coverage	0
Claim No.	C10031214 / JK	Excess	\$0.00
Assign From	JANICE KOH	Assign Date	20/08/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ C 200	C.C	1796
Engine No.	27195031127842	Year of Reg.	13/01/2009
Chassis No.	WDD2040412A209971	Colour	GREY
Odometer	146762 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/40 R18	MICHELIN	6
L/H Front Tyre	225/40 R18	MICHELIN	6
R/H Rear Tyre	225/40 R18	MICHELIN	6
L/H Rear Tyre	225/40 R18	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/08/2024	Inspection Date	19/08/2024
Survey held at	ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4, #04-01 VICOM KAKI BUKIT INSPECTION CENTER, SINGAPORE 415933.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days