



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FC124080350/Uqp3
16 RAFFLES QUAY	Date:	11/09/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 543P	Veh. Inspected	SNM 3926A
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24007345MFCT	Excess	\$0.00
Assign From	BETTY	Assign Date	21/08/2024

### 2. Vehicle Details

Make & Model	HYUNDAI IONIQ 5	C.C	-
Engine No.	-	Year of Reg.	19/09/2023
Chassis No.	PFCKP81BUPF008500	Colour	GREY
Odometer	15722 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/55R19	KUMHO	8
L/H Front Tyre	235/55R19	KUMHO	8
R/H Rear Tyre	235/55R19	KUMHO	8
L/H Rear Tyre	235/55R19	KUMHO	8

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	17/08/2024	Inspection Date	30/08/2024
Survey held at	AUTOBACS CAR CARE (S) PTE LTD 8 KAKI BUKIT AVENUE 4 #08-40/45/46 PREMIER @ KAKI BUKIT SINGAPORE 415875		

### 5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days