



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24080383/Uvh3
75 BRAS BASAH ROAD	Date:	03/09/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 2474Y	Veh. Inspected	SMH 4988C
Policy No.	-	Coverage	0
Claim No.	MT/1292048-001	Excess	\$0.00
Assign From	CHRYLLIS QUAH	Assign Date	23/08/2024

2. Vehicle Details

Make & Model	NISSAN SYLPHY 1.6 CVT	C.C	1598
Engine No.	HR16949093B	Year of Reg.	10/10/2014
Chassis No.	MNTBBAB17Z0020377	Colour	GREY
Odometer	119503 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55R16	DUNLOP	6
L/H Front Tyre	205/55R16	DUNLOP	6
R/H Rear Tyre	205/55R16	DUNLOP	6
L/H Rear Tyre	205/55R16	DUNLOP	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/08/2024	Inspection Date	23/08/2024 (09:50)
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days