



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS GREAT AMERICAN INSURANCE COMPANY	Ref:	CS/GAI24080391/Anp3
3 TEMASEK AVENUE	Date:	02/10/2024
#16-01 CENTENNIAL TOWER	Code:	GAI
SINGAPORE 039190		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 9409B	Veh. Inspected	SLS 1424L
Policy No.	-	Coverage	0
Claim No.	CLMOMVC000004531	Excess	\$0.00
Assign From	JOCELYN	Assign Date	22/08/2024

### 2. Vehicle Details

Make & Model	TOYOTA WISH 1.8 CVT	C.C	1798
Engine No.	2ZR1843844	Year of Reg.	10/10/2016
Chassis No.	JTDGG20W40J005559	Colour	WHITE
Odometer	153953 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	MICHELIN	6
L/H Front Tyre	195/65R15	MICHELIN	6
R/H Rear Tyre	195/65R15	MICHELIN	6
L/H Rear Tyre	195/65R15	MICHELIN	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	21/08/2024	Inspection Date	22/08/2024
Survey held at	GREEN FOREST AUTOMOBILE 8 KAKI BUKIT AVENUE 4 #05-25 PREMIER @ KAKI BUKIT SINGAPORE 415875		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days