



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS INCOME INSURANCE LTD		Ref:		CS/INC24060123/Unh3e2
75 BRAS BASAH ROAD		Date:		16/07/2024
INCOME CENTRE SINGAPORE 189557		Code:		INC
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YQ 2689P	Veh. Inspected	SKT 8613T	
Policy No.	-	Coverage	0	
Claim No.	MT/1281457-002	Excess	\$0.00	
Assign From	NATALIE LEE	Assign Date	18/06/2024	
<b>2. Vehicle Details</b>				
Make & Model	NISSAN SYLPHY (A)	C.C	1598	
Engine No.	HR16959640B	Year of Reg.	25/06/2015	
Chassis No.	MNTBBAB17Z0022938	Colour	GREY	
Odometer	187384 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance (mm)	
R/H Front Tyre	195/60R16	YOKOHAMA	6	
L/H Front Tyre	195/60R16	YOKOHAMA	6	
R/H Rear Tyre	195/60R16	YOKOHAMA	6	
L/H Rear Tyre	195/60R16	YOKOHAMA	6	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/06/2024	Inspection Date	20/06/2024 (11:24AM)	
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				